

NATIONAL TRANSPORTATION SAFETY BOARD

Office of Research and Engineering

Washington, D.C. 20594

May 8, 2008



A. ACCIDENT

Place : Minneapolis, Minnesota
Date : August 1, 2007
Vehicle : I-35W Bridge 9340
NTSB No. : HWY07MH024
Investigator : Mark Bagnard

B. DETAILS

This report displays pre-collapse images containing nodes U10 East and West, L11 East and West, U10' East and West and L11' East and West.



Overviews (East side of the Bridge), Source MNDOT Inspection 2003, D89426-R1-8.jpg



Overviews (West side of the Bridge), Source MNDOT Inspection 2003, D89426-R1-9.jpg



Overviews (West side of the Bridge) , Source Individual, IMG_1500.JPG



Overviews (East side of the Bridge) , Source University of Minnesota, 10.jpg




Overviews (West side of the Bridge), Source University of Minnesota, i35wmiss01.jpg



Overviews (West side of the Bridge) , Source Individual, 2007_0730Riverboat0064.jpg



Overviews (West side of the Bridge), Source Individual, 2007_0730Riverboat0065.jpg



Overviews (West side of the Bridge) , Source Individual, 2007_0730Riverboat0067.jpg



Overviews (East side of the Bridge), Source Individual, DSC07299.JPG




Overviews (East side of the Bridge) , Source Individual, CIMG8723.jpg



Overviews , Source URS (June 2003), DSK1209S.JPG



Overviews (from below of the bridge showing lateral and sway braces), Source University of Minnesota, 8.jpg



Overviews (from below of the bridge showing lateral and sway braces), Source Individual, DSC07297.JPG



L11East , Source University of Minnesota (June 1999), MVC-019F.JPG



L11West , Source URS (June 2003), DSK1113S.JPG



L11West , Source University of Minnesota (June 1999), MVC-014F.JPG




L11'East , Source University of Minnesota (June 1999), MVC-005F.JPG



U10East , Source University of Minnesota (August 1999), MVC-030F.JPG



U10East , Source University of Minnesota (August 1999), MVC-011F.JPG



U10East , Source University of Minnesota (August 1999), MVC-006F.JPG



U10East , Source URS (June 2003), DSK9-26S.JPG




U10East , Source University of Minnesota (August 1999), MVC-010F.JPG



U10East , Source URS (June 2003), DSK9-29S.JPG



U10East , Source URS (June 2003), DSK9-25S.JPG



U10East , Source University of Minnesota (August 1999), MVC-019F.JPG



U10West , Source University of Minnesota (June 1999), MVC-009F.JPG

May 8, 2008

U10-L11 Precollapse
Page 14



U10West , Source URS (June 2003), DSK4-32S.JPG



U10West , Source URS (June 2003), DSK5-02S.JPG



U10West , Source URS (June 2003), DSK5-03S.JPG



U10West , Source URS (June 2003), DSK5-04S.JPG

May 8, 2008

U10-L11 Precollapse
Page 16



U10West , Source URS (June 2003), DSK5-01S.JPG



U10'East , Source URS (June 2003), DSK9-02S.JPG

May 8, 2008

U10-L11 Precollapse
Page 17



U10'East , Source URS (June 2003), DSK9-03S.JPG



U10'West , Source URS (June 2003), DSK4-08S.JPG

May 8, 2008

U10-L11 Precollapse
Page 18



U10'West , Source URS (June 2003), DSK4-09S.JPG



U10'West , Source URS (June 2003), DSK4-06S.JPG

May 8, 2008

U10-L11 Precollapse
Page 19



U10'West , Source URS (June 2003), DSK4-07S.JPG



U10'West , Source URS (June 2003), DSK4-04S.JPG



U10'West , Source URS (June 2003), DSK4-05S.JPG



U10'West , Source URS (June 2003), DSK4-10S.JPG