## PROPELLER LOG BOOK



## SENSENICH PROPELLER MFG. CO. Lititz, Pennsylvania 17543

Internet: http://www.sensenich.com.

THIS LOG BOOK IS TO BE KEPT
WITH THE PROPELLER
FOR RECORDING OF ALL PROPELLER MAINTENANCE WORK PERFORMED

ANNUAL DETAILS NUMBER	INSPECTION OF THIS INSP	HAT THIS PROPELLER HAS BEEN INS AND WAS DETERMINED TO BE IN AIR PECTION CAN BE FOUND ON CARTER	RWORTHY CONDITION, PERTINE!	1T
DATE	TIME	DESCRIPTION OF WORK	SIGNATURE	
TO BE IN AIRW	ORTHY CONDITA DEMONUMBER 62	Type: PIPER PA-18-150, S/N: 1809010, Tach: 929. EN INSPECTED IN ACCORDANCE WITH AN AN ON. PERTINENT DETAILS OF THIS INSPECTION	INUAL INSPECTION AND WAS DETERMINED	) _
	(-10/			
		·		
· · · · · · · · · · · · · · · · · · ·				
-		i i		
	4			
Date: 11/1	4/2007: Aircraft: N	1988PC; Type: PIPER PA-18-150; Tach: 1190.20;	Prop - Type: 76EM8-0-56, S/N: 32000K. Time	
726.70, Si Dressed b	MOH: 263.10	s with a mill file.		
The aircia	ft and/or compone orthy for return to	t identified above was repaired and inspected in a service, Pertinent details of this repair are on file a	at this agency under work order # 6588.	vas
11/14/200	7.ROGER E. SMI			***************************************
UARTER A	MITURUAL I INC. 3	EDRINGTELENIDA	Andrew Control of the	

## DESCRIPTION OF ALL OPERATIONS PERTAINING TO AIRWORTHINESS DIRECTIVES, SERVICE BULLETINS, SERVICE LETTERS, & MINOR ADJUSTMENTS

DATE	TACH • TIME	DESCRIPTION OF WORK	SIGNATURE
Date: 2/25/200 SMOR: 283.10		; Type: PIPER PA-18-150; Tach: 1210.20; Prop - Type:	76EM8-0-56, S/N: 32000K, Time: 746.7
2/25/2008 I Cer	tify that this propel	er has been inspected in accordance with an Annual insp	ection and was determined to be in
airworthy condi Roger E. Smith	tion Pertinent deta	is of this inspection can be found at this agency under w	ork order number 6652
Carter Aircraft I	ncl Sebring FL.		
•			
	-		