

(LT)

VOLUME NO. 1

~~C-9757~~
N144PE
N789UP

LEFT Prop

SECTION IV

PROPELLER

LOG

PROPELLER LOG

1. Make HARTZELL
2. Model RHC-C34F-20F
3. Specification No. _____
4. Date of Manufacture 1983
5. Hub Serial No. EB 1994

BLADE ✓ SN #1 F408600 76"
#2 F40854
#3 F40847

PITCH 19.0° H
14.0° L
84.0 FEATHERED

REPAIRS, ADJUSTMENTS, MODIFICATIONS
ENTRIES. DRAW A DIAGONAL LINE THROUGH ANY UNUSED LINES IN DATE AND TIME COLUMNS.

SIGNATURE

LICENCE NUMBER

10-8-2010 Left propeller log entry for N789UP
Hobbs 1936.3 TAT 8214.9 TSMOH 516.0
Removed this propeller for left side of N789UP for reseal and check at propeller shop.

[Redacted Signature]
Loren Winkelmann

LORAVCO SERVICES

Propeller S/N EB1994 TSN UNK TSO 516.0

This propeller has been serviced as per the 8130-3 tag dated
10/18/2010 under Work Order 99504

Aircraft Propeller Service, Inc.
Wheeling, Illinois

CRS EY2R811K

JAA.5126

10/22/2010 HM 1936.3 ATT 8214.9 TSO 516.0 TT 6761.1

Installed propeller on LT. eng. of N789UP after repair
by Aircraft Propeller Service, Inc. W.O. = 99504. Gnd run ops
and leak check good.

I certify that this work described above has been inspected and is determined to be in an airworthy condition with respect
to the work performed. Pertinent details are on file at this agency under W.O.# R 2141 Date 10/22/2010
Tech/Hobbs, 1936.3 Signed [Redacted]
LORAVCO Services, Inc. Central Illinois Regional Airport, Bloomington, IL 61704
FAA Approved Repair Station #OLKRS711

MR-1

10/22/2010 HM 1946.3 ATT 8224.9 TSO 526.0 TT 6771.1 Removed
propeller from LT. side of N789UP. [Redacted] LORAVCO

Propeller S/N EB1994 TSN 6771.1 TSO 0.0

This propeller has been serviced as per the 8130-3 tag dated
11/23/2010 under Work Order 99712

Aircraft Propeller Service, Inc.
Wheeling, Illinois

CRS EY2R811K

JAA.5126

PROPELLER SERVICE AND

DATE	TIME RUN		TOTAL TIME SINCE OVERHAUL		INSTALLATIONS, INSPECTIONS, NOTE: USE BOTH PAGES AND AS MANY LINES AS REQUIRED FOR COMPLETE
	HRS.	MIN.	HRS.	MIN.	
BROUGHT FORWARD →			12/03/2010		HM 1946.3 ATT 8224.9 TSO 0.0
TSN 6370.1					Installed Propeller on LT. side of N7896A
					after overhaul by Aircraft Propeller Service, Inc. W.O.# 99712.
					2nd run. Ovr and leak check good.

I certify that this work described above has been inspected and is determined to be in an airworthy condition with respect to the work performed. Pertinent details are on file at this agency under W.O.# R7152 Date 12/03/2010
 Hobbs 1946.3 Signed _____
 LORAVCO Services, Inc. Central Illinois Regional Airport, Bloomington, IL. 61704
 FAA Approved Repair Station #OLKR571L MR-1

8/5/2013	HM	2007.6	ATT	8286.2	TSO	61.3	TT	6832.4	Inspected
6th serviced propeller, A.D.'s checked thru 2013-15									

I certify that this work described above has been inspected and is determined to be in an airworthy condition with respect to the work performed and that this Propeller has been inspected in accordance with an Annual and is determined to be in an airworthy condition. Pertinent details are on file at this agency under W.O.# R7614
 Date 08/05/2013 Aircraft Hobbs 2007.6 TTIS 61.3 Signed _____
Synergy Flight Center

**LOGBOOK ENTRY
L/H PROPELLER**

MODEL: PHC-C3VF-2UF
 PROP S/N: EB 1994
 N 789UP
 S/N: 414A 0495

DATE: 10/01/2014
 HOBBS: 2068.3
 SPOH: 122.0
 PTT: 6893.1

SCHEDULED MAINTENANCE

- 1.) Performed an Annual/100 Hour inspection using Cessna 414A maintenance manual & FAR 43 appendix D as a guide.
- 2.) Blended blade nicks I.A.W. Hartzell maintenance manual.
- 3.) Serviced chamber pressure to 42 PSI I.A.W. Hartzell and Cessna 414A maintenance manuals.
- 4.) Lubed propeller with Aeroshell 6 grease.
- 5.) Checked AD's through 2014-19.

With respect to the work performed, this Propeller is approved for return to service.
 Additional details of this work are on file under Work Order # 3009

SIGNED _____

Norman Walters

Ideal Aviation

Cahokia, IL 62206

(F)

CARRIED FORWARD

TOTAL THIS PAGE

TOTAL FROM PREVIOUS SUMMARY

TOTAL SINCE MFG.