

PROPELLER LOGBOOK

PROPELLER MODEL BHC- J2YF/F7694

PROPELLER S/N EF 484B

LOGBOOK # 1



Position	PITCH RANGE
Propeller Model BUC-J2Y F/F7694	High/Feather 35.0°
Propeller S/N EF 454B	Start Lock
Blade Design	Low 14, 6
Blade S/N's No. 1 _ <i>K 828 7.3</i>	Reverse
No. 2 K 82868	Aircraft Manufacturer CARRUS .
No. 3	Aircraft Model SR 20
No.°4	S/N_///0
No. 5	Registration 223C0
No. 6	
Spinner Assembly Part No	

Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.	
1 7	O # 1110 15 DIR MARIO	1298.9 BBS @	INSTAlled New PRAP ON AIRCRAFT N-22.7C. 10 ends 1298,9 Ground Ruy Na Leaks Noted at this to	timp "
-	ATA 05-20 ADs check See AD list The mainte with curren	 lubed per sed thru BW t for full det enance ope t regulation 	2009-08. ails. ration(s) described above were inspected in accordance	
-		on file und	airworthy and is approved for return to service. Privork order 5143. MONTGOMERY AVIATION, INC. 11329 East State Road 32	

*

· •

