

DOCKET NO. **SA- 516**

EXHIBIT NO. **17C**

**NATIONAL TRANSPORTATION SAFETY BOARD
WASHINGTON, D.C**

**DATABASE FOR THE
RECONSTRUCTION OF TWA 800
ALL PARTS HUNG REPORT**

TWA Flight 800: Reconstruction**All Parts Hung Report**

Total parts hung = 837 + 39 = 876

Requested By: NTSB

EXHIBIT NO. 17C

Report Date: Monday, May 19, 1997

Log #	Tag #	FBI #	Date Received	Date Hung	Comments
LF109	Z3102	9/09/96-49	2/24/97	12/31/97	Notch of 6" X 8" cut in floor board 2 holes drilled REMOVED FOR FLOOR
CW314	Z2730	9/22/96-1		5/15/97	Mesh
CW328	Z2827	9/22/96-1		5/15/97	Mesh
CW411	Z2547			5/15/97	Mesh
CW413	Z2677	9/20/96-33		5/15/97	Mesh
CW414	Z2676			5/15/97	Mesh
CW315	Z2685	9/21/96-1		5/15/97	Mesh
CW312	Z2717	9/23/96-5		5/15/97	mesh
CW311	Z2707	9/23/96-5		5/15/97	Mesh
CW412	C2283			5/15/97	Mesh
CW310	Z2729			5/15/97	Mesh
CW316	Z2734	9/22/96-1		5/15/97	Mesh
CW322	Z2735	9/22/96-1		5/15/97	Mesh
CW335	Z4011	11/11/96-58		5/15/97	Mesh
CW334	Z4012	11/14/96-102		5/15/97	Mesh
CW332	Z4003	11/06/96-29		5/15/97	Mesh
CW331	Z4002	11/05/96-16		5/15/97	Mesh
CW330	Z4001	11/06/96-107		5/15/97	Mesh
CW313	Z2732	9/23/96-5		5/15/97	Mesh
CW323	Z2796			5/15/97	Mesh
CW329	Z2828	9/22/96-1		5/15/97	Mesh
CW308	Z2728	9/22/96-1		5/15/97	Mesh
CW337	Z4045	11/20/96-208		5/15/97	Mesh
CW349	Z4053	11/20/96-211		5/15/97	Mesh
CW348	Z4052	11/06/96-81		5/15/97	Mesh
CW347	Z4051	11/06/96-47		5/15/97	Mesh
CW346	Z4050	12/14/96-31		5/15/97	Mesh
CW343	Z4049	11/14/96-81		5/15/97	Mesh
CW342	Z4048	11/11/96-139		5/15/97	Mesh
CW340	Z4047	1/13/97-120		5/15/97	Mesh
CW345	D2091	9/23/96-5		5/15/97	Mesh
CW408	C2282	8/18/96-6		5/15/97	Mesh
CW336	Z4046	11/11/96-40		5/15/97	Mesh
CW309	Z2727	9/22/96-1		5/15/97	Mesh

EXHIBIT NO. 17C

Report Date: Monday, May 19, 1997

Log #	Tag #	FBI #	Date Received	Date Hung	Comments
CW339	Z4044	12/14/96-31		5/15/97	Mesh
CW338	Z4043	11/11/96-139		5/15/97	Mesh
CW306	C196	8/08/96-30		5/15/97	Mesh
CW303	C239	8/09/96-37		5/15/97	Mesh
CW407B	C2266	8/18/96-6		5/15/97	Mesh
CW404	C2269	8/19/96-22		5/15/97	Mesh
CW410	C2270	8/19/96-22		5/15/97	Mesh
CW407A	C2268	8/18/96-6		5/15/97	Mesh
CW305	B2022			5/15/97	Mesh
CW304	B2023	8/08/96-31		5/15/97	Mesh
CW344	D2090	9/22/96-1		5/15/97	Mesh
CW432	Z4081	11/17/96-17		5/15/97	Mesh
CW429	Z2923	9/20/96-33		5/15/97	Mesh
CW425	Z2922	9/20/96-33		5/15/97	Mesh
CW427	C2494	8/19/96-22		5/15/97	Mesh
CW434	C2495	8/18/96-4		5/15/97	Mesh
CW420	C2496	8/19/96-22		5/15/97	Mesh
CW440	Z2494	9/20/96-33		5/15/97	Mesh
CW353	Z4084	1/24/97-52		5/15/97	Mesh
CW428	D2154			5/15/97	Mesh
CW422	Z2926	9/20/96-33		5/15/97	Mesh
CW431	Z2927	9/20/96-33		5/15/97	Mesh
CW433	Z4079	11/14/96-129		5/15/97	Mesh
CW426	C2493	8/18/96-6		5/15/97	Mesh
CW430	D2155	9/26/96-17		5/15/97	Mesh
CW320	D2009			5/15/97	Mesh
CW325	Z2805	9/23/96-5		5/15/97	Mesh
CW324	Z2804	9/22/96-1		5/15/97	Mesh
CW319	D2010			5/15/97	Mesh
CW307	C2370	9/22/96-1		5/15/97	Mesh
CW436	Z4082	12/14/96-41		5/15/97	Mesh
CW405	C2373	8/19/96-22		5/15/97	Mesh
CW438	Z4083	12/09/96-74		5/15/97	Mesh
CW333	Z2829	9/22/96-1		5/15/97	Mesh
CW326	Z2797	10/13/96-3		5/15/97	Mesh
CW317	Z2795	9/20/96-33		5/15/97	Mesh

EXHIBIT NO. 17C

Report Date: Monday, May 19, 1997

Log #	Tag #	FBI #	Date Received	Date Hung	Comments
CW318	Z2798	9/22/96-1		5/15/97	Mesh
CW321	Z2714	9/23/96-5		5/15/97	Mesh
CW423	Z4080	11/17/96-1		5/15/97	Mesh
CW716	A005			4/24/97	
CW1022	C2372	8/11/96-1		4/23/97	RBL 21 CWT Rear spar stiffner
CW1023	Z2814	10/03/96-4		4/23/97	RBL 46 CWT Rear spar stiffner
LF92	C104	8/04/96-56		4/18/97	
CW514	A459	8/17/96-4	2/16/97	4/18/97	
RF42-1	C2463			4/18/97	Cut from rf42
LF127	C2455	8/14/96-22	2/19/97	4/18/97	Laying on floor
RF142	Z2886	9/28/96-2	2/19/97	4/18/97	
LF189	B009	8/03/96-85		4/18/97	
LF14H	C2475	8/18/96-6		4/18/97	2 holes drilled to attach
CW504	A236	8/08/96-14		4/18/97	HOLE 2" X .5" FWD BENDING
LF39B	C112	8/05/96-70		4/18/97	
LF81	D2082	8/03/96-85		4/18/97	
LF1	B2006	No FBI #		4/18/97	Check date with Reconstruction log - it was before 4/18
LF123	Z2880	9/21/96-1	2/19/97	4/18/97	laying on floor
RF20	A212	8/06/96-46		4/18/97	
CW512	A238	8/08/96-14	2/16/97	4/18/97	
LW03	C108	8/04/96-111		4/18/97	Piece cut and hung
LF14M	D2136	8/08/96-31		4/18/97	Sooted, no penetrations
LF122	D2106	8/09/96-37	2/19/97	4/18/97	Laying on floor
LF186E	D2153	9/11/96-4		4/18/97	Alex assembled
CW236	Z2755	9/24/96-16	3/3/97	4/18/97	CW 236 was taken by the FBI to the bomb tech room on 3/3/97 - Returned 4/17
CW531	X4003	11/16/96-155		4/18/97	
RF122O	X3001	9/28/96-1		4/18/97	
CW513	A500	8/19/96-11	2/16/97	4/18/97	
LF162-1	A2070	8/12/96-4		4/18/97	
LF7B	B170	8/05/96-34		4/18/97	
LF82K	C2411			4/18/97	
LF186A	Z2919	9/12/96-2		4/18/97	Alex put together
RF124F	X4044	11/16/96-189		4/18/97	
	X4076	11/20/96-179		4/18/97	
LF186B	Z4077	11/16/96-26		4/18/97	Alex put together
CW145B	Z2914	9/20/96-33		4/18/97	

EXHIBIT NO. 17C

Report Date: Monday, May 19, 1997

Log #	Tag #	FBI #	Date Received	Date Hung	Comments
LF186D	Z4078	11/11/96-78		4/18/97	Alex assembled
RF76	Z2526	9/10/96-4	2/16/97	4/18/97	Right stub frame FS 1060 - near CW104 - Placed on reconstruction
LW04	C2293	8/05/96-70		4/18/97	Piece cut and hung
LF71A	Z2537	9/11/96-4		4/18/97	Labeled as LF71B - but tag indicates LF71A
	Z2920	9/21/96-1		4/18/97	Alex put together
LF185	D2152	8/24/96-7		4/17/97	
FBM4A	A2044			4/17/97	Red piece in green zone
RF121B	A2050	8/03/96-85		4/16/97	
RF171	D2157	8/10/96-9		4/16/97	
CW530D	E2038	7/19/96		4/16/97	
CW530B	E2037	10/11/96-6		4/16/97	
CW530A	E2036	7/19/96		4/16/97	Drilled 4 holes
LF155	D2124	9/25/96-2		4/16/97	
CW530E	A2060	8/05/96-2		4/16/97	
RF124R	D2080	8/08/96-31		4/16/97	Actually the left side
LF154	C2469	8/26/96-36		4/16/97	
LF184A	D2151	9/28/96-1		4/15/97	
LF57	A709			4/15/97	
LJ	Z2908	9/26/96-17		4/15/97	
LF184B	Z2918	9/19/96-1		4/15/97	
RF3M	B334	8/10/96-9		4/15/97	
RF3K	B2101	8/07/96-15		4/15/97	
RF3L	B2102	8/07/96-15		4/15/97	
LF190	B2049	8/03/96-85		4/15/97	
RF3N	B2029	8/07/96-15		4/15/97	
RF170	X4084	2/03/97-320		4/15/97	
LF188	A489	8/19/96-11		4/14/97	
LF187	X4085	11/29/96-176		4/14/97	
LF176	A213	8/06/96-46		4/14/97	
LF175	A2069	8/17/96-4		4/14/97	
LF22-04	B160	8/05/96-5		4/14/97	
LF177	A175	8/06/96-1		4/14/97	
CW246	C2158	8/09/96-37	3/26/97	3/26/97	
CW245	Z3466	9/23/96-5	3/26/97	3/26/97	
LF12A	A126	8/04/96-66	3/2/97	3/24/97	
LF55E	D2036		3/19/97	3/22/97	

EXHIBIT NO. 17C

Report Date: Monday, May 19, 1997

Log #	Tag #	FBI #	Date Received	Date Hung	Comments
RF121A	X4006	11/20/96-161	3/2/97	3/22/97	
LF180B	Z4072	11/08/96-34	3/22/97	3/22/97	
LF179B	Z4071	11/06/96-77	3/17/97	3/22/97	
LF179C	Z2904	9/20/96-33	3/17/97	3/22/97	
RF122F	W4007	11/29/96-131	3/21/97	3/22/97	
LF180A	C1689	8/30/96-21	3/22/97	3/22/97	
FBM34	D2144	10/07/96-1	3/16/97	3/21/97	
LF24A	A2017	NO FBI #	3/2/97	3/21/97	
cw716	Z2903	9/24/96-16	3/21/97	3/21/97	
LF87G	Z2844		3/3/97	3/21/97	
FBM35	Z2898	9/21/96-1	3/16/97	3/21/97	2 holes drilled
FBM36	Z2899	9/21/96-1	3/16/97	3/21/97	2 holes drilled
CW507	C2186	8/18/96-6	3/4/97	3/21/97	
CW508	C2137		3/4/97	3/21/97	
CW505	C2140		3/4/97	3/21/97	
CW510	C2141	8/19/96-22	3/4/97	3/21/97	
CW506	C2135		3/4/97	3/21/97	
RF57	A710	8/24/96-8	3/21/97	3/21/97	
CW402	C2026	8/18/96-6	3/4/97	3/21/97	
CW509	C2018		3/4/97	3/21/97	
CW516	C2226	8/19/96-22	3/4/97	3/21/97	
RF122S	C077	8/14/96-10	3/21/97	3/21/97	
RF3D	B189	8/06/96-2	3/6/97	3/21/97	
LF170	C2483	8/26/96-36	3/12/97	3/20/97	
LW52	C2176	8/18/96-6	3/20/97	3/20/97	
RF160	C039	8/11/96-1	3/17/97	3/20/97	
RF122T	X4034	11/20/96-123	3/2/97	3/20/97	
LF55B	A2049	8/22/96-7	3/19/97	3/20/97	
LF55A	A744	8/24/96-8	3/20/97	3/20/97	
LF129	D2108	10/2/96-1	2/19/97	3/20/97	
FBM24C	B031	8/03/96-85	3/12/97	3/20/97	
LF55B	A449	8/22/96-7		3/20/97	
RF109C	D2022	8/10/96-16	3/2/97	3/20/97	
RF169A	C2491	8/24/96-7	3/19/97	3/20/97	2 holes drilled
RF122Q	A2003	8/19/96-23	3/2/97	3/20/97	
FBM39	Z2900	9/30/96-1	3/20/97	3/20/97	1 hole drilled

EXHIBIT NO. 17C

Report Date: Monday, May 19, 1997

Log #	Tag #	FBI #	Date Received	Date Hung	Comments
LF128I	Z2885	9/28/96-2	2/28/97	3/20/97	
FBM40I	C2488	8/14/96-9	3/16/97	3/20/97	2 holes drilled
LF88A	C2434	8/30/96-1	3/1/97	3/20/97	
RF169B	C2492	8/24/96-2	3/20/97	3/20/97	2holes drilled
RF162I	D2139		3/19/97	3/19/97	
LF16B-1I	C2485	8/04/96-111	3/12/97	3/19/97	sooted and the piece was cut from LF16b
RF122H	W4014	11/29/96-39	3/2/97	3/19/97	
RF168I	X4082	2/03/97-332	3/19/97	3/19/97	
RF122U	A540	8/22/96-7	3/2/97	3/19/97	
RF122V	A713	8/24/96-8	3/3/97	3/19/97	
LF55C	D2035		3/19/97	3/19/97	
FBM41I	Z2901	9/19/96-1	3/16/97	3/19/97	2 holes drilled
RF122L	X4023	11/16/96-158	3/2/97	3/19/97	
LF171I	D2141	9/25/96-2	3/12/97	3/19/97	
RF122B	B343	8/10/96-9	3/2/97	3/19/97	
RF165I	Z4066	11/08/96-33	3/12/97	3/19/97	
FBM42I	Z2670	9/19/96-1	3/16/97	3/19/97	
FBM37I	Z3403	9/20/96-33	3/16/97	3/19/97	
LF169I	Z2895	9/12/96-2	3/15/97	3/19/97	
RF122W	Z2865	9/30/96-1	3/11/97	3/19/97	
RF122K	X4022	11/29/96-162	3/2/97	3/19/97	
LF168B	Z2897	9/12/96-2	3/15/97	3/19/97	
RF122E	X4024	11/14/96-214	3/2/97	3/19/97	
FBM45I	D2146	8/16/96-9	3/16/97	3/19/97	
RF122I	X4030	11/29/96-238	3/2/97	3/19/97	
RF122M	X4032	11/23/96-4	3/2/97	3/19/97	
RF122R	X4033	11/20/96-8	3/2/97	3/19/97	
RF122D	X4028	11/23/96-128	2/3/97	3/19/97	
LF172I	D2142	8/24/96-7	3/12/97	3/19/97	
RF122J	X4031	1/13/97-42	3/2/97	3/19/97	
FBM44I	Z2902	9/09/96-49	3/19/97	3/19/97	3 holes drilled
LF168I	Z2896	9/20/96-33	3/15/97	3/19/97	the first part (A)
RF122N	Z5051	10/17/96-2	3/2/97	3/19/97	
FBM43I	C056	8/14/96-9	3/16/97	3/19/97	
LF183I	W4011	2/03/97-181	3/19/97	3/19/97	
LF37A	A614	8/12/96-4	3/19/97	3/19/97	cut made by s-38 for support

EXHIBIT NO. 17C

Report Date: Monday, May 19, 1997

Log #	Tag #	FBI #	Date Received	Date Hung	Comments
RF122C	A204	8/06/96-46	3/2/97	3/19/97	
FBM38	D2145	9/28/96-1	3/16/97	3/19/97	
RF122A	B292	8/08/96-31	3/2/97	3/19/97	
RF124B	A2056	8/17/96-4	3/18/97	3/18/97	
RF123M	X4043	11/23/96-175	3/12/97	3/18/97	rivets popped for reconst.
LF74	X2201	9/23/96-5	3/18/97	3/18/97	
RF124L	X4046	11/20/96-164	3/18/97	3/18/97	2 holes drilled
RF123L	X4042	11/29/96-260	3/12/97	3/18/97	rivets popped for reconst.
RF123J	Z4026	11/08/96-18	3/12/97	3/18/97	rivets popped for reconst.
RF124J	X4051	11/23/96-129	3/18/97	3/18/97	
RF124N	D2079		3/18/97	3/18/97	
RF123K	A2053	8/22/96-7	3/12/97	3/18/97	rivets popped out for reconst
LF14P	C2231	8/29/96-4	3/18/97	3/18/97	4 holes drilled
RF124M	A2055	8/17/96-4	3/18/97	3/18/97	2 holes drilled
RF124Q	X4048	11/16/96-213	3/18/97	3/18/97	
RF124H	X4045	11/23/96-175	3/18/97	3/18/97	
RF123F	X4039	11/14/96-150	3/12/97	3/18/97	rivets popped for reconst.
RF123B	X4036	11/20/96-166	3/12/97	3/18/97	rivets popped for reconst.
RF123C	X4037	11/20/96-67	3/12/97	3/18/97	rivets popped out for reconst.
RF123A	X4035	11/23/96-131	3/12/97	3/18/97	rivets popped for rivets
RF111H	Z2853	9/24/96-16	3/2/97	3/18/97	drilled 2 holes in rf111h and 1 additional hole in rf22
LF14J	Z2891	9/21/96-1	3/6/97	3/18/97	1 hole drilled
RF124O	X4047	11/29/96-267	3/18/97	3/18/97	
LF14I	C2392	8/4/96-111	3/18/97	3/18/97	3 holes drilled
RF124D	A485	8/16/96-10	3/17/97	3/18/97	4" piece cut to allow installation
RF124A	A2004	8/19/96-23	3/18/97	3/18/97	
LF179D	Z2925	9/20/96-33	3/18/97	3/18/97	
LF182	X4080	2/03/97-304	3/18/97	3/18/97	
RF167	D2148	7/29/96	3/18/97	3/18/97	1 hole drilled by wje
RF124P	Z4059	11/08/96-21	3/18/97	3/18/97	
LF97	X4083	1/09/97-67	3/18/97	3/18/97	2 holes in lf97 and 2 holes drilled in lf89 for rivets
RF124I	A739	8/24/96-8	3/18/97	3/18/97	
RF123E	A424	8/14/96-11	3/12/97	3/18/97	rivets popped out for reconst
RF124T	Z3573	9/28/96-1	3/18/97	3/18/97	cut 6" piece off end - hung seperately
LF14S	Z2893	10/13/96-3	3/18/97	3/18/97	1 hole drilled
LF14N	Z2892	9/21/96-1	3/18/97	3/18/97	2 holes drilled

EXHIBIT NO. 17C

Report Date: Monday, May 19, 1997

Log #	Tag #	FBI #	Date Received	Date Hung	Comments
RF124E	A2067	8/17/96-4	3/18/97	3/18/97	
RF124C	X3002	9/28/96-1	3/17/97	3/18/97	
LF22-25	A2063	8/03/96-85	3/17/97	3/17/97	
LF86H	C2428	8/12/96-3	3/17/97	3/17/97	2 holes drilled
LF45D	C2490	8/29/96-4	3/17/97	3/17/97	
LF45B	C2387	8/20/96-12	3/17/97	3/17/97	
LF178D	Z4073	11/14/96-83	3/17/97	3/17/97	
LF178E	Z2907	9/09/96-49	3/17/97	3/17/97	
LF22-7	D2048	8/10/96-9	3/17/97	3/17/97	
LF82D	Z2851	9/26/96-17	3/17/97	3/17/97	2 holes drilled
CW123	Z2674	9/19/96-1	3/17/97	3/17/97	
LF22-17	D2072	8/10/96-9	3/17/97	3/17/97	
RF118	X4001	11/14/96-211	3/17/97	3/17/97	
LF178C	Z2906	9/09/96-49	3/17/97	3/17/97	
LF86E	Z2857	9/04/96-1	3/17/97	3/17/97	2 holes drilled
LF66	C2322	8/26/96-36	3/17/97	3/17/97	3 holes drilled
RF3J	B220	8/07/96-15	3/17/97	3/17/97	1 hole drilled
LF178B	Z2905		3/17/97	3/17/97	
LF86I	Z2855	9/22/96-1	3/17/97	3/17/97	1 hole drilled
LF86D	C2425	8/26/96-36	3/17/97	3/17/97	2 holes drilled
LF86J	C2438	8/26/96-36	3/17/97	3/17/97	1 holes drilled
LF178I	C2487	8/22/96-5	3/17/97	3/17/97	
RF108	A2033	8/19/96-23	3/17/97	3/17/97	
CW144D	D2147	9/22/96-1	3/16/97	3/17/97	
CW145J	Z2917	9/20/96-33	3/14/97	3/17/97	
LF22-8	B2081	8/07/96-15	3/17/97	3/17/97	
LF86B	C2423	8/19/96-22	3/17/97	3/17/97	2 holes drilled
LF178F	Z4074	11/14/96-83	3/17/97	3/17/97	
LF167B	Z4065	11/06/96-120	3/17/97	3/17/97	2 holes drilled
LF86F	C2426	8/30/96-23	3/17/97	3/17/97	2 holes drilled
LF86G	C2427	8/26/96-36	3/17/97	3/17/97	2 holes drilled
LF178H	Z2912		3/17/97	3/17/97	
LF22-16	D2043	8/10/96-9	3/17/97	3/17/97	
LF178G	Z2911	9/30/96-1	3/17/97	3/17/97	
r164	D2140	9/30/96-24	3/17/97	3/17/97	SOOTED
LF86C	Z2850	9/21/96-1	3/17/97	3/17/97	2 holes drilled

EXHIBIT NO. 17C

Report Date: Monday, May 19, 1997

Log #	Tag #	FBI #	Date Received	Date Hung	Comments
LF167A	Z4064	11/11/96-172	3/17/97	3/17/97	2 holes drilled
LF22-36	D2047		3/17/97	3/17/97	
LF105	D2098	9/26/96-17	2/18/97	3/17/97	
CW171	Z4069	11/11/96-49	3/17/97	3/17/97	
LF14R	C2478	8/26/96-36	3/17/97	3/17/97	
LF181B, LF181D	C664	8/22/96-5	3/17/97	3/17/97	
RF51	C2002	8/18/96-6	3/17/97	3/17/97	PENETRATION SECTION REMOVED BY THE FBI IN OCTOBER
CW177	Z4068	11/11/96-40	3/17/97	3/17/97	
LF14Q	D2138	9/26/96-17	3/17/97	3/17/97	
LF54C	C1017	8/23/96-15	3/17/97	3/17/97	4 holes drilled
LF14K	D2134		3/17/97	3/17/97	
CW176	Z4018	11/17/96-2	3/17/97	3/17/97	
LF22-3	B335	8/12/96-4	3/16/97	3/17/97	
LF187A	Z3115	9/09/96-49	3/17/97	3/17/97	
LF22-24	B332	8/12/96-4	3/16/97	3/16/97	
LF22-06	B233	8/07/96-15	3/16/97	3/16/97	
RF3G	B007	8/03/96-85	3/16/97	3/16/97	5 holes drilled
LF22-13	B234	8/07/96-15	3/16/97	3/16/97	1 hole drilled
LF23	B325	8/12/96-4	3/16/97	3/16/97	1 hole drilled
LF96	X4081	1/09/97-41	3/2/97	3/16/97	
CW139	Z2736		3/15/97	3/16/97	
CW181	Z4070	11/05/96-33	3/16/97	3/16/97	
LF22-19	B013	8/03/96-85	3/16/97	3/16/97	
RF3I	B327	8/10/96-9	3/16/97	3/16/97	
LF22-05	B005	8/03/96-85	3/16/97	3/16/97	
LF22-12	D2041		3/16/97	3/16/97	
LF22-9	A2061	8/03/96-85	3/16/97	3/16/97	
LF22-15	D2042		3/16/97	3/16/97	
LF22-11	B232	8/07/96-15	3/16/97	3/16/97	
LF22-22	B2073	8/03/96-145	3/16/97	3/16/97	
LF22-28	B2079		3/16/97	3/16/97	
LF22-35	D2046		3/16/97	3/16/97	
LF22-30	B2080			3/16/97	
LF22-26	D2044	8/08/96-31	3/16/97	3/16/97	
LF22-32	D2045	8/10/96-9	3/16/97	3/16/97	
LF22-14	B018	8/03/96-85	3/16/97	3/16/97	

EXHIBIT NO. 17C

Report Date: Monday, May 19, 1997

Log #	Tag #	FBI #	Date Received	Date Hung	Comments
LF22-10	D2071	8/06/96-3	3/16/97	3/16/97	1 hole drilled
LF20	B180	8/06/96-2	3/16/97	3/16/97	cut three holes to fit reconstruction
LF22-01	B290	8/08/96-31	3/13/97	3/16/97	1 hole drilled
LF22-37	D2149	8/10/96-9	3/16/97	3/16/97	
RF19B	A268	8/10/96-9	3/2/97	3/16/97	
RF92	B294	8/08/96-31	3/16/97	3/16/97	1 HOLE TO LOOK AT - wired in
LF22-31	D2073	8/10/96-9	3/16/97	3/16/97	
LF22-3	B2036	8/05/96-34	3/16/97	3/16/97	
LF22-21	B2044	8/03/96-145	3/16/97	3/16/97	
LF22-18	B2043	8/03/96-145	3/16/97	3/16/97	
LF22-29	A2064	8/03/96-85	3/16/97	3/16/97	
LF22-02	B298	8/08/96-31	3/16/97	3/16/97	2 holes drilled - 1 HOLE TO LOOK AT
LF22-27	B201	8/06/96-2	3/16/97	3/16/97	
LF22-20	B249	8/07/96-15	3/16/97	3/16/97	
LF22-34	B209	8/07/96-15	3/16/97	3/16/97	drilled 1 hole - enlarged 1 rivet hole
RF3H	B2017		3/16/97	3/16/97	7 holes drilled
RF25	B289	8/08/96-31	3/16/97	3/16/97	2 holes drilled
RF70	B167	8/05/96-17	3/16/97	3/16/97	2 - 1" DIA. HOLES - several saw cuts - 2 holes drilled for RF95
LF22-23	B251	8/07/96-15	3/16/97	3/16/97	
RF18C	B141	8/04/96-65	3/15/97	3/15/97	2 2' DIA. HOLES - Piece cut at Sta 515 for reconstruction
LF06B	B2016		3/15/97	3/15/97	
RF18G	B218	8/07/96-15	3/15/97	3/15/97	2 holes drilled
CW175	Z4067	1/17/97-2	3/15/97	3/15/97	
RF24	B333	8/12/96-4	3/14/97	3/14/97	drilled 1 hole
LF86N	D2075		3/14/97	3/14/97	
LF80	Z3256	9/19/96-1	3/14/97	3/14/97	
LF86P	Z2858	9/21/96-1	3/14/97	3/14/97	
RF3C	B223	8/07/96-15	3/14/97	3/14/97	
RF3E	B221	8/07/96-15	3/14/97	3/14/97	1 - 5" DIA. HOLE - 1 1" DIA. HOLE
RF6B	B240	8/07/96-15	3/14/97	3/14/97	
RF28	C217	8/08/96-30	2/17/97	3/14/97	
RF3A	B250	8/07/96-15	3/14/97	3/14/97	8 - 3/8" holes drilled - 4 HOLES TO BE LOOKED AT - BOTH SIDES
RF6C	B318	8/08/96-31	3/14/97	3/14/97	
RF3F	B011	8/04/96-65	3/14/97	3/14/97	drilled 2 1/4" holes
RF3B	B008	8/03/96-85	3/14/97	3/14/97	
CW524	Z2832	9/21/96-1	3/13/97	3/13/97	used existing holes

EXHIBIT NO. 17C

Report Date: Monday, May 19, 1997

Log #	Tag #	FBI #	Date Received	Date Hung	Comments
CW239	Z4007	11/11/96-70	3/13/97	3/13/97	
CW240	Z4008	11/11/96-78	3/11/97	3/13/97	
CW528	Z2868	10/30/96-7	3/13/97	3/13/97	used existing hole
LF12C	A136	8/05/96-2	3/13/97	3/13/97	
CW237	Z2831	9/12/96-1	3/11/97	3/13/97	pieces next to it needed another drill hole
LF04, RF04	B103	8/03/96-145	3/12/97	3/12/97	cut 2 slices for rib - 28 holes drilled
LF99	X4079	11/20/96-34	3/12/97	3/12/97	
LF51	C642	8/22/96-5	3/11/97	3/11/97	3' DIA. HOLES AT STRINGER ROWS
CW201	C2147	8/08/96-14	3/11/97	3/11/97	
LF91	Z5112	10/30/96-2	3/11/97	3/11/97	
LF93	Z2833		3/11/97	3/11/97	
LF90	Z2825	9/20/96-33	3/11/97	3/11/97	
RF66	C2156	8/26/96-36	3/11/97	3/11/97	
LF43	A453	8/17/96-4	3/11/97	3/11/97	
LF94	X4005	11/20/96-31	3/11/97	3/11/97	
LF64	Z2520	9/09/96-49	3/11/97	3/11/97	
LF89	Z5058	10/17/96-2	3/11/97	3/11/97	
LF82P	C2415	8/26/96-36	3/11/97	3/11/97	NEEDS TO BE LOOKED AT - PILLOWING AND CURLING
LF70B	Z3119	9/09/96-49	3/11/97	3/11/97	SEVERAL HOLES AND CURLED EDGES
LF82Q	C730	8/26/96-36	3/11/97	3/11/97	
LF87I	Z2845	9/09/96-49	3/11/97	3/11/97	
LF87A	Z2843	9/21/96-1	3/11/97	3/11/97	
LF87D	C2333	8/22/96-5	3/11/97	3/11/97	
LF63	Z2519		3/11/97	3/11/97	VARIOUS HOLES IN SKIN - DOCUMENTED IN STRUCTURES DOCUMENT
CW218	C2161	8/10/96-16	3/11/97	3/11/97	
LF87E	Z2760	9/12/96-2	3/11/97	3/11/97	
LF87B	Z2759	9/25/96-2	3/11/97	3/11/97	HOLE IN SKIN 1' X 1' FORWARD EDGE
LF82R	C2416	8/30/96-13	3/11/97	3/11/97	drilled 1 hole
LF82N	C2413	8/20/96-12	3/11/97	3/11/97	
LF87F	Z2779	9/21/96-1	3/11/97	3/11/97	1/2" X HOLE NEAR FORWARD EDGE
LF88D	A2028	8/06/96-46	3/11/97	3/11/97	
CW206	C2160	8/08/96-31	3/11/97	3/11/97	
LF31, LF162	A601	8/12/96-4	3/11/97	3/11/97	cut from A601 (LF31)
LF82O	C2414	8/24/96-7	3/11/97	3/11/97	
LF100	X4078	11/23/96-149	3/11/97	3/11/97	
LF41	C101	8/04/96-64	3/11/97	3/11/97	Separated LF41 into 2 pieces for mock up

EXHIBIT NO. 17C

Report Date: Monday, May 19, 1997

Log #	Tag #	FBI #	Date Received	Date Hung	Comments
LF70A	Z2518	9/12/96-2	3/11/97	3/11/97	TIGHTLY CURLED EDGES NEAR UPPER FORWARD CORNER
LF82B	C2408	8/19/96-22	3/11/97	3/11/97	2 small holes both 1"
LF82C	C2409	8/22/96-5	3/11/97	3/11/97	TEAR 3' X 1' 9 (IMPORTANT) METAL EMBEDDED
LF87C	Z2758	9/20/96-33	3/11/97	3/11/97	
LF87H	Z2859	9/09/96-49	3/11/97	3/11/97	
RF19A	A166	8/06/96-1	3/2/97	3/10/97	1 HOLE
LF36	A260	8/08/96-14	3/10/97	3/10/97	
LF50	A131	8/05/96-2	3/10/97	3/10/97	
RF52A	C646	8/22/96-5	3/10/97	3/10/97	1 SMOOTH OBLONG HOLE
LF88M	Z3786	10/18/96-3	3/10/97	3/10/97	
LF165	A541	8/22/96-7	3/10/97	3/10/97	
LF44	A536	8/20/96-15	3/10/97	3/10/97	
RF52C	C2102	8/22/96-5	3/10/97	3/10/97	
LF166	A242	8/08/96-14	3/1/97	3/10/97	
LF58A	A734	8/24/96-8	3/10/97	3/10/97	
LF164	A029	8/03/96-85	3/10/97	3/10/97	
LF163	A404	8/14/96-9	3/10/97	3/10/97	cut tracks - 2 holes drilled
RF46	A476	8/19/96-11	3/10/97	3/10/97	2 holes drilled
RF6A	B2004	8/03/96-85	3/10/97	3/10/97	
RF52B	C365	8/14/96-9	3/10/97	3/10/97	12' X 14' HOLE
RF52G	C307	8/12/96-3	3/10/97	3/10/97	
LF37B	A182	8/06/96-1	3/10/97	3/10/97	
LF88L	C2443	8/30/96-1	3/10/97	3/10/97	
LF88I	Z2860	9/22/96-1	3/10/97	3/10/97	
RF125	X4069	12/14/96-115	3/10/97	3/10/97	2 holes drilled
LF88C	C2442	8/19/96-22	3/10/97	3/10/97	1 hole drilled
LF58B	A2047	8/17/96-4	3/10/97	3/10/97	2 holes drilled
RF52D	C2435	8/26/96-2	3/10/97	3/10/97	
RF117	Z4076	11/11/96-20	3/3/97	3/10/97	2 holes drilled
RF111B	C2429	8/26/96-36	3/7/97	3/7/97	1 hole drilled
RF7	A033	8/03/96-85	3/7/97	3/7/97	
CW147	C2382	8/19/96-22	2/11/97	3/7/97	
RF21	A2031	8/11/96-1	3/7/97	3/7/97	drilled out 4 rivet holes plus 2 carriage holes
LF82V	C2420	8/30/96-1	3/7/97	3/7/97	
RF111A	C2424	8/30/96-3	3/7/97	3/7/97	1 hole drilled
LF24B	A252	8/08/96-14	3/7/97	3/7/97	

EXHIBIT NO. 17C

Report Date: Monday, May 19, 1997

Log #	Tag #	FBI #	Date Received	Date Hung	Comments
RF111C	Z2852	9/21/96-1	3/7/97	3/7/97	
LF54B	C2389	8/23/96-15	3/7/97	3/7/97	1 hole drilled - 2 holes drilled in LF54A for attachment
RF64	C2153	8/26/96-36	3/6/97	3/6/97	
RF150	C2465	8/26/96-36	3/6/97	3/6/97	
LF137	C2457	8/26/96-36	2/23/97	3/6/97	2 SMALL HOLES
RF149	C2462	8/22/96-5	2/24/97	3/6/97	1 hole drilled - 2 hole drilled in RF16A for attachment - 1 SMALL HOLE ON EDGE
LF45C	C2256	8/29/96-4	3/1/97	3/6/97	
LF138	Z2887	9/24/96-16	2/25/97	3/6/97	
CW153	D2081	8/16/96	3/6/97	3/6/97	
RF145	Z3640	10/13/96-3	3/6/97	3/6/97	2 HOLES
RF124K	W4008	1/13/97-158	3/5/97	3/6/97	
LF82F	C2410	8/14/96-9	3/6/97	3/6/97	1 HOLE 1/4' X 1/2' INSIDE OUT
RF124S	X4049	11/23/96-130	3/5/97	3/6/97	
RF144	D2120	8/09/96-37	2/25/97	3/6/97	
RF129	D2092	8/08/96-31	2/18/97	3/6/97	
LF140	Z2872	9/30/96-1	3/6/97	3/6/97	
LF82T	C2418	8/19/96-22	3/6/97	3/6/97	1 hole drilled
LF82E	C315	8/14/96-9	3/6/97	3/6/97	1 TEAR - 1 PUNCTURE HOLES 1' LONG
LF88B	Z2846	9/24/96-16	3/6/97	3/6/97	1 HOLE
LF95	X4008	11/23/96-9	3/2/97	3/6/97	3 holes drilled
LF82U	Z2848	9/25/96-2	3/6/97	3/6/97	
LF82A	Z2738	9/24/96-16	3/6/97	3/6/97	2 holes drilled
LF98	X4077	11/29/96-162	3/6/97	3/6/97	3 holes drilled
LF82W	Z2849	9/23/96-5	3/6/97	3/6/97	
RF5	A071	8/03/96-85	3/6/97	3/6/97	5 holes drilled
LF159	D2132	9/25/96-2	2/28/97	3/6/97	
LF88H	Z1787	10/07/96-1	3/6/97	3/6/97	
CW164	W4013	11/08/96-15	3/6/97	3/6/97	
RF43	C2477	8/15/96-8	3/5/97	3/5/97	1 hole drilled
LF104	Z2877	9/20/96-33	2/18/97	3/5/97	
RF63	C1081	8/26/96-36	3/1/97	3/5/97	
LF120	D2104	9/22/96-1	2/24/97	3/5/97	
RF95	Z3072	9/11/96-4	3/4/97	3/5/97	1 flange cut 12" x 10" - POSSIBLE PENETRATION ON FORWARD EDGE
RF35	A2068	8/14/96-11	3/2/97	3/5/97	
LF119	D2103	9/22/96-1	2/18/97	3/5/97	
RF131	C2450	8/18/96-6	2/18/97	3/5/97	

EXHIBIT NO. 17C

Report Date: Monday, May 19, 1997

Log #	Tag #	FBI #	Date Received	Date Hung	Comments
LF101	C2039	8/18/96-6	2/25/97	3/5/97	
LF103	D2097	9/11/96-4	2/18/97	3/5/97	
CW704A	C2448		3/5/97	3/5/97	
RF67	C1674	8/30/96-23	3/4/97	3/5/97	
LF116	C2452	8/20/96-12	2/18/97	3/5/97	1 SMALL HOLE
LF117	C2453	8/23/96-15	2/18/97	3/5/97	
LF14D	C2440	8/05/96-70	3/5/97	3/5/97	1 hole drilled
LF115	C2451	8/26/96-36	2/18/97	3/5/97	
LF6A	A141	8/05/96-2	3/2/97	3/5/97	25 holes drilled
RF32	A605	8/12/96-4	3/2/97	3/5/97	4 holes drilled
LF139	D2118	9/26/96-17	2/28/97	3/5/97	
CW1018	Z2766	9/24/96-16	3/5/97	3/5/97	
LW07, CW106, CW401	C114	8/05/96-70	2/14/97	3/5/97	
LF118	D2102	8/24/96-7	2/18/97	3/5/97	
CW704B	C2447	7/27/96	3/5/97	3/5/97	
CW223	C2168		3/4/97	3/4/97	1 hole drilled in CW201
CW229	C2165	8/19/96-22	3/4/97	3/4/97	
LF107	C2132	8/09/96-37	3/4/97	3/4/97	
RF53C	C1025	8/23/96-15	3/4/97	3/4/97	
RF111D	C2430	8/30/96-23	3/2/97	3/4/97	1 hole drilled
LF14B, CW1009, CW211	C2481	8/08/96-30	3/4/97	3/4/97	Keel beam - 2 pieces CW1009 is section of wing tank floor - 6 holes drilled
RF130	D2096	9/10/96-4	2/18/97	3/4/97	2 holes drilled
LF114	D2101	8/11/96-1	2/18/97	3/4/97	2 holes drilled
RF53B	C686	8/23/96-15	3/1/97	3/4/97	
RF109B	C164	8/06/96-46	3/2/97	3/4/97	
LF14C	C2479		3/4/97	3/4/97	14A & C - 1 hole drilled to bolt together - part fell off LF14E during reconstruction D2137 part of the keelbeam
RF1	c2498		3/2/97	3/4/97	6 holes drilled - side frames cut between 860 & 880 and between 800 & 820 2 HOLES TO LOOK AT
RF109A	C2379	8/05/96-70	3/2/97	3/4/97	
LF14F	D2135	9/22/96-1	3/4/97	3/4/97	4 holes drilled - 1 HOLE DAMAGE
RF133	C2454	8/05/96-70	2/18/97	3/4/97	oblong hole in attached piece of floor beam
RF132	D2105	8/04/96-111	2/18/97	3/4/97	
LF14L	C2476	8/04/96-56	3/4/97	3/4/97	2 holes drilled
RF52E	C2094	8/22/96-5	3/3/97	3/4/97	
CW238	Z4006	11/11/96-25	3/4/97	3/4/97	1 hole drilled - 1 hole CW201
RF35	A421	8/14/96-11	3/4/97	3/4/97	5 holes drilled - 1 hole drilled RF37

19-May-97 6:37 PM

NTSB Reconstruction All Parts Hung Report
 UPPER CASE = DEFORMATION PRIOR TO RECONSTRUCTION
 lower case = alterations made for reconstruction

EXHIBIT NO. 17C

Report Date: Monday, May 19, 1997

Log #	Tag #	FBI #	Date Received	Date Hung	Comments
LF14A, LF55D	A2048		3/2/97	3/4/97	
LF106	C026	8/09/96-37	3/4/97	3/4/97	1 SMALL HOLE
LF158	C2472	8/04/96-56	3/3/97	3/3/97	3 holes drilled - was attached to landing gear
LF92-1, LF151	C2486	8/04/96-56	3/3/97	3/3/97	2 holes drilled
LF156	C2470	8/04/96-56	3/3/97	3/3/97	3 holes drilled - was attached to landing gear
RF154	D2125	9/26/96-17	3/3/97	3/3/97	1 hole drilled
CW231	Z2715	9/23/96-5	3/3/97	3/3/97	1 hole drilled in CW207
RF111E	C2431	8/30/96-23	3/2/97	3/3/97	
CW228	Z2710	9/23/96-5	3/3/97	3/3/97	1 hole drilled - 1 hole drilled in CW201
CW226	Z2709		3/3/97	3/3/97	1 hole drilled
LF157	C2471	8/04/96-56	2/28/97	3/3/97	3 holes drilled - off landing gear
LF12B	A181	8/06/96-1	3/2/97	3/3/97	3 holes drilled - at 970, piece unbolted and bolted back 4" saw cut and bend @ arch
CW204, CW1007	C159		2/14/97	3/3/97	3 holes drilled
RF156	D2127	9/25/96-2	3/3/97	3/3/97	2 holes drilled
CW208	C2234	8/18/96-6	3/3/97	3/3/97	2 holes drilled
RF147	C2459	8/26/96-36	3/3/97	3/3/97	2 holes drilled and marked
RF111G	C2433	8/24/96-7	3/2/97	3/3/97	
CW203, CW1005	C193	8/08/96-30	3/2/97	3/3/97	5 holes drilled
LF59	C708	8/26/96-4	3/3/97	3/3/97	1 hole drilled to attach to LF85
CW215, CW503, RW02	C251	8/08/96-30	3/3/97	3/3/97	1 HOLE TO LOOK AT BY DRY BAY ACCESS HOLE - 2 holes drilled
CW212	C2157	8/18/96-6	3/3/97	3/3/97	2 holes drilled
CW219	C2159	8/09/96-37	3/3/97	3/3/97	1 hole drilled
CW209	C2169	8/08/96-30	3/3/97	3/3/97	2 holes drilled
CW210	C2149	8/26/96-34	3/3/97	3/3/97	1 existing hole enlarged - 1 hole drilled in CW222 to accomodate
CW217	C2093	8/22/96-5	3/3/97	3/3/97	1 hole in CW217 and CW204 drilled
RF158	D2128	9/26/96-17	3/3/97	3/3/97	1 hole drilled
RF53E	D2058	8/04/96-64	3/1/97	3/3/97	
CW224	Z2750	9/21/96-1	3/3/97	3/3/97	1 hole drilled and 1 hole in CW222 drilled
CW222	Z2751	9/27/96-1	3/3/97	3/3/97	1 existing hole drilled
CW230	Z2752	9/22/96-1	3/3/97	3/3/97	1 hole drilled in CW207
CW227	Z2753	9/22/96-4	3/3/97	3/3/97	1 hole drilled - additional hole to CW201
CW235	Z2754	9/24/96-16	3/3/97	3/3/97	1 hole drilled
LF85	Z2721	9/02/96-11	3/3/97	3/3/97	1 hole drilled to attach to LF 59
CW225	Z2756		3/3/97	3/3/97	3 holes drilled - also 2 holes drilled in CW201
CW234	Z2757		3/3/97	3/3/97	1 hole drilled - add 1 hole drilled to CW215
CW232	Z3376	9/22/96-1	3/3/97	3/3/97	4 holes drilled

19-May-97 6:37 PM

NTSB Reconstruction All Parts Hung Report
 UPPER CASE = DEFORMATION PRIOR TO RECONSTRUCTION
 lower case = alterations made for reconstruction

EXHIBIT NO. 17C

Report Date: Monday, May 19, 1997

Log #	Tag #	FBI #	Date Received	Date Hung	Comments
RF53A	D2057	8/04/96-64	3/1/97	3/3/97	enlarged hole for 1/4" rod attachment
RF111F	C2432		3/2/97	3/3/97	1 hole drilled in RF 31 for rivet attachment
CW233	Z2703		3/3/97	3/3/97	1 hole drilled - 1 hole also drilled in CW216
LF5	A022	8/03/96-85	3/3/97	3/3/97	6 holes drilled - 5 used
CW205	C218	8/08/96-30	3/1/97	3/2/97	5 holes drilled - 2 HOLES TO LOOK AT - LBL (1.5" X 2") RBL (3" X 1")
CW202, CW3A	C186	8/08/96-15	3/2/97	3/2/97	3 holes drilled
CW220	Z2673	9/21/96-1	3/1/97	3/2/97	5 holes drilled
CW216	C2148		3/1/97	3/2/97	2 holes drilled
RF31	B2014	8/04/96-64	2/28/97	3/1/97	1 HOLE MARKED - 5 holes drilled
LF54A	C2388	8/04/96-111	3/1/97	3/1/97	2 holes drilled
CW221	Z3492	9/24/96-16	3/1/97	3/1/97	
RF40	C2330	8/05/96-70	3/1/97	3/1/97	2 holes drilled
CW207	C238	8/09/96-37	3/1/97	3/1/97	
RF151	B2048	8/04/96-54	2/28/97	2/28/97	1 HOLE
LF148	D2122		2/28/97	2/28/97	
LF150	D2123	9/06/96-17	2/28/97	2/28/97	
RF155	D2126	9/26/96-17	2/28/97	2/28/97	
RF10A	C106	8/04/96-111	2/28/97	2/28/97	cut at FS. 1630 3 holes drilled
RF148	D2129	9/25/96-2	2/28/97	2/28/97	
LF147	C2466	8/26/96-36	2/28/97	2/28/97	
RF153	Z2889	9/26/96-17	2/28/97	2/28/97	
RF159	D2130	9/26/96-17	2/28/97	2/28/97	
LF144	D2121	9/25/96-2	2/28/97	2/28/97	
LF152	C2088	8/20/96-12	2/28/97	2/28/97	
RF152	C2467	8/05/96-70	2/28/97	2/28/97	
LF153	C2458	8/26/96-36	2/28/97	2/28/97	3.5" x 7" TEAR OR HOLE
RF71	C2215	8/29/96-4	2/28/97	2/28/97	
RF157	Z2890	9/26/96-17	2/28/97	2/28/97	
LF141	Z2888	9/26/96-17	2/28/97	2/28/97	
RF10A	C2473		2/28/97	2/28/97	2 holes diled for lifting and 12 holes drilled to hang
LF108	D2099	9/28/96-1	2/18/97	2/28/97	pressure deck web Sta. 1309 to 1338 LBL13 to 56 - 4 holes drilled
LF61	C1083	8/26/96-36	2/28/97	2/28/97	
RF10A	C2474		2/28/97	2/28/97	rear portion top with 2 windows - 3 holes drilled
LF142	Z2869	9/25/96-2	2/27/97	2/27/97	
LF143	B2046	8/04/96-54	2/27/97	2/27/97	
LF145	C2484	8/26/96-36	2/27/97	2/27/97	1 HOLE TO LOOK AT

EXHIBIT NO. 17C

Report Date: Monday, May 19, 1997

Log #	Tag #	FBI #	Date Received	Date Hung	Comments
LF29	C227	8/08/96-30	2/26/97	2/27/97	3 HOLES AT FS 60 DAMAGEpiece cut at FS 1630 and two holes drilled for fastening
LF45A	C976	8/20/96-12	2/27/97	2/27/97	1 HOLE 3" AND A 3" LONG TEAR - 5 holes drilled
RF59	C236	8/09/96-37	2/21/97	2/27/97	2 holes drilled and 1 saw cut
LF146	C729	8/26/96-36	2/27/97	2/27/97	
RF65	C1661	8/29/96-4	2/27/97	2/27/97	13 holes drilled
LF149	C739	8/26/96-36	2/26/97	2/27/97	(ONE HOLE DAMAGE - two holes drilled
RF22	C2334		2/27/97	2/27/97	slot cut 4" x 9" for reconst. 6 holes drilled
LF67C	C2345	8/18/96-6	2/26/97	2/26/97	
RF119	C2464	8/04/96-55	2/26/97	2/26/97	2 holes drilled
LF2	C002	8/02/96-23	2/25/97	2/26/97	Holes identified and marked - piece cut at FS. 1630 to fit and 4 holes drilled lifting and 33 holes to fasten
LF92	C2468		2/26/97	2/26/97	three holes drilled
LF86L	Z2842		2/26/97	2/26/97	
LF86K(B)	C2441	8/11/96-2	2/26/97	2/26/97	
lf82m	Z2550	9/11/96-4	2/26/97	2/26/97	
LF67B	Z2548	9/12/96-2	2/26/97	2/26/97	Joins LF67A at Sta.1241 - source C-309Z
LF71B	Z3268	9/19/96-1	2/26/97	2/26/97	three holes drilled
LF69	Z2586	9/16/96-2	2/25/97	2/25/97	1 HOLE 8"X1" INWARD BEND + 1 1" DIA. HOLE - 4 holes for fastners and 2 drilled lholes
RF114B	Z2854		2/16/97	2/25/97	1 holes drilled - 1 additional hole added to RF14
LF102	Z3005	9/08/96-2	2/25/97	2/25/97	4 holes drilled
LF67A	Z3304	9/12/96-2	2/25/97	2/25/97	2 holes drilled
LF40	C802	8/15/96-8	2/20/97	2/25/97	6 holes drilled in LF113 to accommodate LF40
LF39A	C860	8/17/96-7	2/25/97	2/25/97	PUNCTURE INSIDE OUT - 11 holes for fastners 2 addiional holes to fasten LF67A
CW167	C332	8/12/96-3	2/24/97	2/24/97	
CW1015	Z2652		2/15/97	2/24/97	
CW168	D2116	8/08/96-30	2/24/97	2/24/97	test
RF60	C1049	8/24/96-7	2/21/97	2/24/97	2 holes drilled TWO HOLES TO LOOK AT
RF42	C845	8/16/96-5	2/24/97	2/24/97	4 holes drilled for lifting-22 holes drilled for fastening-saw cut stiffner and frame at 1438 to accomodate arch-cut above door to facilitate angle-cut top of RF17 at 1350 & 1250 bolt hole
RF134	C809	8/15/96-8	2/24/97	2/24/97	Three holes drilled
LF111	C689	8/23/96-15	2/24/97	2/24/97	3 holes drilled
CW1024	C2038	8/18/96-6	2/15/97	2/24/97	
CW722	D2117	9/11/96-4	2/21/97	2/23/97	SWB# 2 @ lower cord the fracture matches CW 706 that has a B2002 tag
RF36	C142	8/06/96-46	2/16/97	2/21/97	1 hole drilled
LF110	D2100	9/22/96-1	2/21/97	2/21/97	2 holes drilled
RF127	C069	8/14/96-10	2/21/97	2/21/97	three holes drilled
LF113	Z2879	9/19/96-1	2/21/97	2/21/97	4 holes drilled

EXHIBIT NO. 17C

Report Date: Monday, May 19, 1997

Log #	Tag #	FBI #	Date Received	Date Hung	Comments
LF112	Z2878	9/28/96-2	2/21/97	2/21/97	4 holes drilled
CW1105	Z2826	10/09/96-1	2/13/97	2/21/97	
RF128	C414	8/14/96-9	2/21/97	2/21/97	6 holes drilled LB floorbeam cut at FS 1428 and bent back @ 2 locations - 1 FRACTURE LINE IN FLOORBEAM
CW815	Z2774	9/09/96-49	2/2/97	2/20/97	
CW1101	C2402		2/13/97	2/20/97	
CW823	Z4037	11/16/96-25	2/20/97	2/20/97	
LF17	C109	8/04/96-111	2/19/97	2/20/97	6 Drill holes
CW1103	Z2749	9/28/96-2	2/20/97	2/20/97	
CW818	Z2513	9/09/96-49	2/20/97	2/20/97	
CW1106	Z2773	9/27/96-2	2/13/97	2/20/97	
CW1104	Z2702	9/22/96-1	2/20/97	2/20/97	
CW820	Z2793	9/20/96-33	2/20/97	2/20/97	
CW819	D2008		2/20/97	2/20/97	
CW816	Z2780	9/08/96-2	2/20/97	2/20/97	
CW822	Z4015	11/20/96-208	2/20/97	2/20/97	
CW802	C2164		2/20/97	2/20/97	
CW824	Z4038	11/14/96-62	2/20/97	2/20/97	
CW821	W4009	1/17/97-16	2/20/97	2/20/97	
LF16B, CW1006	C2136	8/04/96-111	2/15/97	2/20/97	Saw cut away from CW1006 prior to reconstruction
CW829	Z4061	2/10/97-131	2/20/97	2/20/97	
CW810	Z2762		2/20/97	2/20/97	
CW809	Z3550	9/27/96-1	2/20/97	2/20/97	
CW1109	Z2873	9/30/96-1	2/20/97	2/20/97	
CW806	C2344	8/19/96-22	2/20/97	2/20/97	
CW1102	C2077	8/20/96-12	2/20/97	2/20/97	
CW825	Z4039	11/14/96-83	2/20/97	2/20/97	Attached to CW809 mid spar
CW1107	Z4058	11/11/96-119	2/20/97	2/20/97	
CW1108	Z4014	11/06/96-2	2/14/97	2/20/97	
CW1016	Z3297	9/21/96-1	2/19/97	2/19/97	
CW805	B2024	8/08/96-31	2/19/97	2/19/97	
CW828	Z4062	2/03/97-212	2/19/97	2/19/97	
CW814	Z2711	9/23/96-5	2/19/97	2/19/97	
CW1008	C1051	8/24/96-7	2/15/97	2/19/97	
CW827	Z4041	11/11/96-70	2/19/97	2/19/97	
CW812	Z2794		2/19/97	2/19/97	
CW808	Z2719	9/22/96-1	2/19/97	2/19/97	

EXHIBIT NO. 17C

Report Date: Monday, May 19, 1997

Log #	Tag #	FBI #	Date Received	Date Hung	Comments
CW811	Z2782	9/22/96-1	2/19/97	2/19/97	
CW813	Z2712		2/19/97	2/19/97	
CW826	Z4040	11/14/96-107	2/19/97	2/19/97	
CW1011	C2145		2/15/97	2/18/97	
CW719	D2095		2/18/97	2/18/97	
CW1012	C2144	8/09/96-31	2/15/97	2/18/97	
CW1003	C2143	8/08/96-30	2/15/97	2/18/97	
CW1010, CW241	C2138	8/09/96-37	2/15/97	2/18/97	
CW721	C2449		2/18/97	2/18/97	
LF16A, CW1002	C2146	8/04/96/111	2/15/97	2/18/97	
CW1004	C2139	8/08/96-30	2/15/97	2/18/97	
CW718	D2094	9/22/96-1	2/18/97	2/18/97	
CW1013	C2284		2/18/97	2/18/97	
CW720	Z3729	10/17/96-1	2/18/97	2/18/97	
CW145G	Z2916	9/20/96-33		2/18/97	
CW145E	Z2915			2/18/97	
CW149	Z2788		2/11/97	2/18/97	
CW146	Z2787		2/11/97	2/18/97	
CW144A	Z2784		2/11/97	2/18/97	Pieces A one of five a-e
CW145	Z2785		2/11/97	2/18/97	Pieces E and G hung 2/18/97- J hung 3/17/97 this piece is designated as A
CW1017	Z2726	9/20/96-33	2/15/97	2/18/97	
CW131	C2391	8/19/96-22	2/11/97	2/18/97	
CW112	C2229		2/11/97	2/18/97	
CW1014	Z2656	9/20/96-33	2/15/97	2/18/97	
CW211, CW1009	C1031	8/23/96-15	2/14/97	2/18/97	
RF126	C2460	8/04/96-111	2/18/97	2/18/97	RF126-1 original attachment
CW161	Z4033	11/11/96-94	2/11/97	2/18/97	
RF38	C811	8/15/96-8	2/18/97	2/18/97	4" X 4" plate cut for fods and 6" of frame cut out at FS1350 for arch 2" X 1" triangle cut off to place RF31
CW155A	Z4027	11/06/96-104	2/11/97	2/18/97	
CW160	Z4042	12/09/96-74	2/11/97	2/18/97	
CW157	Z4036	11/20/96-221	2/11/97	2/18/97	
CW1019	Z2767	9/19/96-1	2/15/97	2/18/97	
CW162	C2445	8/19/96-22	2/11/97	2/18/97	
CW154	Z4022	11/29/96-213	2/11/97	2/18/97	
CW1020	Z2768	9/19/96-1	2/15/97	2/18/97	

EXHIBIT NO. 17C

Report Date: Monday, May 19, 1997

Log #	Tag #	FBI #	Date Received	Date Hung	Comments
CW1411	Z2769	9/21/96-1	2/11/97	2/18/97	
CW717	D2093	9/26/96-17	2/18/97	2/18/97	
RF23	C299	8/10/96-16	2/16/97	2/17/97	
CW502	A021	8/03/96-85	2/16/97	2/17/97	2 HOLES ONE SMALL .5X1 FWD BENDING
CW515	A618	8/16/96-10	2/16/97	2/17/97	
CW504A	C2108	8/22/96-5	2/16/97	2/17/97	
RF114C	Z3215	9/30/96-1	2/17/97	2/17/97	
CW520	X4004	11/16/96-170	2/16/97	2/17/97	
CW712	Z2815	9/21/96-1	2/14/97	2/17/97	
RF34	C067	8/14/96-9	2/17/97	2/17/97	Saber saw cut on front frame for arch
RF41	C848	8/16/96-5	2/17/97	2/17/97	
CW522	A456		2/16/97	2/17/97	Marked CW522
CW501	A018	8/03/96-85	2/16/97	2/17/97	NUMEROUS SMALL HOLES MOSTLY FWD BENDING
CW525	X4053	11/20/96-199	2/16/97	2/17/97	
CW711	Z3259	9/19/96-1	2/14/97	2/17/97	
CW526	A2066		2/16/97	2/17/97	
CW710	Z2540	9/11/96-4	2/14/97	2/17/97	
CW713	Z3103	9/09/96-49	2/14/97	2/17/97	
CW521	X4052	11/20/96-172	2/16/97	2/17/97	
CW519	Z3029	9/08/96-2	2/16/97	2/17/97	2 SMALL HOLES 1 LARGE (TEAR 2" X .25")
CW709	C2265	8/11/96-1	2/14/97	2/17/97	
CW708	C2275	8/08/96-68	2/14/97	2/17/97	
CW703	A490	8/19/96-11	2/14/97	2/17/97	
CW701	C874	8/16/96-5	2/14/97	2/17/97	CW 341 part of CW701
CW714	Z2874	9/22/96-1	2/14/97	2/17/97	
CW705	C2170		2/14/97	2/17/97	
CW706	B2002	8/04/96-64	2/14/97	2/17/97	
RF14	C157	8/06/96-46	2/16/97	2/16/97	front frame slightly below window level cut
CW1021	Z2772	9/10/96-4	2/15/97	2/16/97	
RF114A	Z3568	9/28/96-1	2/16/97	2/16/97	
CW518, LF38	C851	8/16/96-5	2/15/97	2/15/97	LF38 is 4 large pieces
RF37, CW517	C801	8/15/96-8	2/15/97	2/15/97	
CW127	D2017	8/08/96-31	2/14/97	2/14/97	
CW901	C970	8/20/96-12	2/13/97	2/14/97	
CW915	Z2809	9/20/96-1	2/14/97	2/14/97	
CW910	Z2724	9/22/96-1	2/13/97	2/14/97	

EXHIBIT NO. 17C

Report Date: Monday, May 19, 1997

Log #	Tag #	FBI #	Date Received	Date Hung	Comments
CW922	Z2681	9/19/96-1	2/13/97	2/14/97	
CW908	Z2679	9/19/96-1	2/13/97	2/14/97	
CW912	Z2725	9/21/96-1	2/14/97	2/14/97	
CW921	Z2875	9/23/96-5	2/14/97	2/14/97	
CW911	A2054	8/08/96-14	2/13/97	2/14/97	
CW128	D2018	8/08/96-31	2/14/97	2/14/97	
CW917	Z2811	9/23/96-5	2/14/97	2/14/97	
CW904	C2177		2/14/97	2/14/97	
CW906	Z3272	9/19/96-1	2/13/97	2/14/97	
CW907	Z2662	9/19/96-1	2/13/97	2/14/97	
CW923	C2446	8/22/96-5	2/14/97	2/14/97	
CW924	D2119	10/02/96-1	2/14/97	2/14/97	1 hole for rivet
CW926	Z4060	11/14/96-69	2/14/97	2/14/97	
CW913	Z3394	9/24/96-16	2/14/97	2/14/97	
CW925	Z4056	11/11/96-127	2/14/97	2/14/97	
CW909	Z2741	9/22/96-1	2/13/97	2/14/97	
CW905	C2107	8/22/96-5	2/14/97	2/14/97	
CW148	Z2737	9/22/96-1	2/14/97	2/14/97	
LW15, CW 403	C2175	8/19/96-22	2/14/97	2/14/97	
CW918	Z2812	9/22/96-1	2/14/97	2/14/97	
CW903	C2131		2/13/97	2/14/97	
CW919	Z2813	9/22/96-1	2/14/97	2/14/97	
CW914	Z2808	9/23/96-5	2/14/97	2/14/97	
CW104, CW301, CW707	C2151	8/15/96-8	2/14/97	2/14/97	Removing short lengths, 2' to 4' long from Stringers 24,25,26 to ease const.
CW902	C897	8/16/96-5	2/13/97	2/14/97	
CW807	Z2720	9/22/96-1	2/14/97	2/14/97	Abbutting CW801 contains 3 drill holes on fracture
CW916	Z2810	9/23/96-5	2/14/97	2/14/97	
CW715	Z4057	11/23/96-215	2/12/97	2/14/97	
CW620	X4010	11/20/96-16	2/11/97	2/13/97	
RF77	Z2505	9/09/96-49	1/2/97	2/13/97	
CW607	Z2506	9/09/96-49	2/12/97	2/13/97	
CW645	D2078		2/11/97	2/13/97	
CW606	Z3045	9/09/96-49	2/12/97	2/13/97	
CW637	Z4017	11/11/96-53	2/12/97	2/13/97	
CW632	Z4019	11/06/96-59	2/11/97	2/13/97	
CW642	X4019	11/16/96-140	2/11/97	2/13/97	

19-May-97 6:37 PM

NTSB Reconstruction All Parts Hung Report
 UPPER CASE = DEFORMATION PRIOR TO RECONSTRUCTION
 lower case = alterations made for reconstruction

EXHIBIT NO. 17C

Report Date: Monday, May 19, 1997

Log #	Tag #	FBI #	Date Received	Date Hung	Comments
CW601	C868	8/17/96-7	2/12/97	2/13/97	1 1/2 DIA. HOLE AND VARIOUS PUNCTURES
RF17	C2278		2/12/97	2/13/97	Stringers cut for reconstr. S 24,25,26 also del. tags c-189,190
CW628	Z2864	9/22/96-1	2/11/97	2/13/97	
CW634	Z2863	9/21/96-1	2/12/97	2/13/97	
CW631	X4020	11/20/96-38	2/11/97	2/13/97	
CW629	Z4020	11/14/96-55	2/11/97	2/13/97	
CW627	X4018	11/14/96-198	2/11/97	2/13/97	
CW644	X4017	12/14/96-92	2/11/97	2/13/97	
CW641	X4071	11/16/96-206	2/11/97	2/13/97	
CW621	X4011	11/29/96-237	2/11/97	2/13/97	
CW605	C2172	8/19/96-22	2/12/97	2/13/97	
CW625	X4016	11/20/96-111	2/11/97	2/13/97	
CW626	X4015	11/20/96-45	2/11/97	2/13/97	
CW604	A475	8/19/96-11	2/12/97	2/13/97	2" X 3/4" HOLE
CW622	X4014	11/23/96-135	2/11/97	2/13/97	
CW643	A180	8/06/96-1	2/11/97	2/13/97	
CW623	X4013	11/20/96-191	2/11/97	2/13/97	
CW615	Z2862	9/20/96-33	2/11/97	2/13/97	
CW618	Z2870	9/21/96-1	2/11/97	2/13/97	
CW610	Z2764	10/03/96-4	2/12/97	2/13/97	
CW611	Z2765	9/30/96-1	2/12/97	2/13/97	
RW8, CW803	C183	8/08/96-15	2/12/97	2/13/97	
CW105	C188	8/08/96-15	2/11/97	2/13/97	see comments RF 17
CW612	Z2763	10/03/96-4	2/12/97	2/13/97	
CW613	D2003	9/30/96-1	2/12/97	2/13/97	
CW602	A210	8/06/96-46	2/12/97	2/13/97	3" X 1" HOLE
CW614	D2011		2/12/97	2/13/97	
CW619	Z2783		2/11/97	2/13/97	
CW609	Z2671	9/09/96-1	2/12/97	2/13/97	
CW639	Z2669		2/11/97	2/13/97	
CW302	C2279		2/12/97	2/13/97	See Comments RF17
CW630	X4026	11/29/96-268	2/11/97	2/13/97	
CW638	X4070	11/20/96-144	2/11/97	2/13/97	
CW608	A533	8/20/96-15	2/12/97	2/13/97	
CW1001	C2280		2/12/97	2/13/97	See Comments RF17
CW633	Z2871	9/08/96-2	2/11/97	2/13/97	

EXHIBIT NO. 17C

Report Date: Monday, May 19, 1997

Log #	Tag #	FBI #	Date Received	Date Hung	Comments
CW603	A227	8/06/96-46	2/12/97	2/13/97	
CW635	Z4021	11/11/96-27	2/11/97	2/13/97	
CW640	X4027	1/09/97-60	2/11/97	2/13/97	
CW624	X4012	12/01/96-28	2/11/97	2/13/97	
CW616	A2059	8/19/96-11	2/11/97	2/13/97	
CW636	Z4023	11/08/96-11	2/11/97	2/13/97	
CW165	Z4013	11/06/96-98	2/12/97	2/12/97	was CW137
CW132	Z2823	9/20/96-33	2/11/97	2/11/97	
CW133	Z2822	9/20/96-33	2/11/97	2/11/97	
	C2016	8/19/96-22	2/11/97	2/11/97	
CW122	Z3347	9/19/96-1	2/11/97	2/11/97	
CW126	Z2722		2/11/97	2/11/97	
CW142	Z2668		2/11/97	2/11/97	
CW125	Z2723	9/21/96-1	2/11/97	2/11/97	
CW120	C2327	8/19/96-22	2/11/97	2/11/97	
CW109	C2014	8/19/96-22	2/11/97	2/11/97	
CW124	Z2675	9/21/96-1	2/11/97	2/11/97	
CW119	C2167	8/8/96-30	2/11/97	2/11/97	
CW716	Z2876	9/12/96-2	2/11/97	2/11/97	
CW107	C2023	8/18/96-6	2/11/97	2/11/97	
	C2024		2/11/97	2/11/97	
CW150	Z4005	11/11/96-27	2/11/97	2/11/97	
CW801, CW102, CW702	C224	8/08/96-30	2/11/97	2/11/97	Abutting CW807 contains 3 drill holes on fracture
CW103	C221	8/08/96-30	2/11/97	2/11/97	
CW152	Z4010	11/14/96-78	2/11/97	2/11/97	
CW108, CW804	C2027	8/18/96-6	2/11/97	2/11/97	
CW158B	Z4031	11/14/96-55	2/11/97	2/11/97	
CW158A	Z4030	11/05/96-5	2/11/97	2/11/97	
CW116	C2166	9/8/96-30	2/11/97	2/11/97	
CW143	Z2770	10/03/96-4	2/11/97	2/11/97	
CW115	Z3089	9/11/96-4	2/11/97	2/11/97	
CW151	Z4009	11/11/96-79	2/11/97	2/11/97	
CW113, CW817	C2233	8/18/96-6	2/11/97	2/11/97	
CW130	Z2507	9/09/96-49	2/11/97	2/11/97	
CW118	Z3035	9/08/96-2	2/11/97	2/11/97	

EXHIBIT NO. 17C

Report Date: Monday, May 19, 1997

Log #	Tag #	FBI #	Date Received	Date Hung	Comments
CW117	Z3036	9/8/96-2	2/11/97	2/11/97	
CW135	Z3211	9/30/96-1	2/11/97	2/11/97	
CW155B	Z4028	11/11/96-79	2/11/97	2/11/97	
CW166	Z4004	11/06/96-12	2/11/97	2/11/97	was CW138
CW163	Z4034	11/14/96-78	2/11/97	2/11/97	
CW110	C2227	8/18/96-6	2/11/97	2/11/97	
CW111	C2228	8/18/96-6	2/11/97	2/11/97	
CW156	Z4029	11/11/96-115	2/11/97	2/11/97	
CW159	Z4032	12/14/96-29	2/11/97	2/11/97	
CW106	C2007	8/18/96-6	2/11/97	2/11/97	
CW140	Z2771	10/03/96-4	2/11/97	2/11/97	
CW101	C808	8/15/96-8	2/10/97	2/10/97	right end forms hole 1" with CW104
CW129	Z2747		2/10/97	2/10/97	
CW121	C413	8/14/96-9	2/10/97	2/10/97	
CW114	Z3028	9/08/96-2	2/10/97	2/10/97	

Additional Pieces

Log #	Tag #	FBI #	Date Received	Date Hung	Comments
1	RF173B Z2932	9/26/96-17	4/19/97	5/19/97	Lwr half of window forging Sta 1580 to 1600 R/H
2	CW173 Z4094	11/11/96-4	4/18/97	5/19/97	
3	CW172 Z4093	11/11/96-63	4/18/97	5/19/97	
4	CW250 Z4091	3/24/97-243	4/17/97	4/18/97	LWR skin CWT RBL75 STR13 OUTBD End of CW-236
5	CW723 C2328	8/18/96-6	4/19/97	5/19/97	SWB#2 LBL 94-127 LWR Chord Segment
6	RF172 C2505	8/24/96-7	4/18/97	5/18/97	Sta 1600 frame R/H
7	RF173A Z4095	11/6/96-58	4/19/97	5/18/97	Skin below window Sta 1580 to 1600 R/H
8	FBM1 A2072	10/18/96-001	4/16/97	4/16/97	Cargo Compartment Fire Bottle (large)
9	CW248 Z4085	8/14/97-4	3/21/97	4/17/97	Was LF 31
10	CW194C Z4090	2/13/97-112	4/7/97	5/19/97	Wing Center Section lower wing sking segment RBL3to RBL13, Just forward of mid spar by 4"
11	CW194A Z4087	1/24/97-9	4/10/97	4/17/97	S-29 Wing Center Section upper
12	CW194B A466	9/9/96-49	4/10/97	4/17/97	S-29 Wing Center Section upper
13	CW194E Z3136	8/17/96-4	4/10/97	4/17/97	Upper stringer 32&33 Wing center section
14	RF174 D2160	8/8/96-31	4/24/97	4/17/97	Upper S-29 wing center section
15	LF67E Z2931	9/21/96-1	4/24/97	4/17/97	Upper S-30 wing center section
16	LF67D Z4092	11/17/96-12	4/24/97	4/24/97	Fuselage skin Sta 660 to 680 below str 16 to 18L
17	LF86A C2422	8/26/96-36	4/24/97	4/24/97	Fuselage skin above overwing longeron betwn sta 1328 to 1340
18	CW1022 Z2814	10/3/96-4	4/17/97	4/23/97	Fuselage skin at fwd lwr corner of main entry door 3L
19	CW1023 C2372	8/11/96-1	4/17/97	4/23/97	Retrieved from bomb tech- fuselage skin str 24L to 26L sta 1394 & aft
20	CW1025 Z2936	10/30/96-2	4/24/97	4/23/97	RBL 21 CWT Rear spar stiffener
21	CW351	3/17/97-14	3/22/97	4/24/97	RBL 46 CWT Rear spar stiffener
22	CW172 Z4093	11/11/96-63	5/1/97	5/18/97	
23	CW173 Z4094	11/11/96-4	5/1/97	5/1/97	
24	CW352			5/15/97	Mesh
25	CW327			5/15/97	Mesh
26	CW350			5/15/97	Mesh
27	CW416			5/15/97	Mesh
28	CW417			5/15/97	Mesh
29	CW418			5/15/97	Mesh
30	CW419			5/15/97	Mesh
31	CW421			5/15/97	Mesh
32	CW424			5/15/97	Mesh
33	CW439			5/15/97	Mesh
34	CW437			5/15/97	Mesh
35	CW435			5/15/97	Mesh
36	CW406			5/15/97	Mesh
37	CW415			5/15/97	Mesh

EXHIBIT NO. 17C

HUNG BY

	Frequency	Percent	Valid Percent	Cumulative Percent
Valid Alex Lemishko	3	.4	.4	.4
Arnie Reimer	5	.7	.7	1.1
BE	2	.3	.3	1.4
Bill Nugent	138	18.6	18.6	20.0
Bob Desantis	81	10.9	10.9	30.9
Bob Whittington	5	.7	.7	31.6
Brad Morrison	5	.7	.7	32.3
David Nixon	5	.7	.7	33.0
Dennis Santiago	4	.5	.5	33.5
Dennis Santigo	1	.1	.1	33.6
Depak Joshi	1	.1	.1	33.8
Dick Arold	49	6.6	6.6	40.4
Gary Graham	4	.5	.5	40.9
Howard Hill	18	2.4	2.4	43.4
Joe Zot	2	.3	.3	43.6
John Smith	49	6.6	6.6	50.3
John Swanson	1	.1	.1	50.4
Jon Mc Gromley	7	.9	.9	51.4
Jon McGormly	1	.1	.1	51.5
Jon McMclosky	1	.1	.1	51.6
Larry Jackson	36	4.9	4.9	56.5
Mike Kessler	19	2.6	2.6	59.1
Mike Koob	228	30.8	30.8	89.9
Rocky miller	4	.5	.5	90.4
Steve Michael	24	3.2	3.2	93.6
Terry Sweeney	44	5.9	5.9	99.6
Vinnie Cocca	3	.4	.4	100.0
Total	740	100.0	100.0	
Total	740	100.0		