



NTSB RECORD OF CONVERSATION

Kate Benhoff
Air Safety Investigator
General Aviation Accident Investigation Division, AS-20

Date: April 16, 2019
Person Contacted: Swaid Rahn (Director of Maintenance and co-owner of flight school)
NTSB Accident Number: GAA19CA176

The following is a summary of a telephone conversation with the above mentioned:

The Director of Maintenance reported that a fire extinguisher was located behind the copilot's seat in a pocket. He added that the owner of the airplane removed the fire extinguisher about a week after the accident, after the airplane was released.