



RECORD OF CONVERSATION

December 31, 2012

NTSB Accident Number: ERA12FA127, Fort Lauderdale, Florida

On this date I spoke by telephone with the first officer, Mr. Thomas Hamer, Jr., to augment his written statement.

Mr. Hamer stated that he did not assist with the controls during the flight. When asked if he or the captain pulled the aileron/spoiler disconnect T-handle during the flight, he stated that he hurried out of the cockpit and may have accidentally hit it with his one of his shoes.

Paul R. Cox
Senior Air Safety Investigator