

Michael Huhn
Air Safety Investigator
Western Pacific Region

Date: January 31, 2011
Person Contacted: Mr. Larry Sayers (Right Front Seat Passenger)
NTSB Accident Number: WPR11GA115

Interviewers: Deputy Bernstein/Deputy Gardner,
Date: 1/31/11
Time: 1452 MST
Location: University Medical Center

Narrative:

The following is a synopsis of the information provided by Mr. Sayers in an in-person interview on this date:

- Larry Sayers (PCWIN project, PC employee)
- Seated in RH Front seat
- Purpose of flight site survey
- Touched down, kind of bumped forward, started to rotate to the right
- Tower site was uphill from attempted landing site
- Pilot "cussed"
- No specific problem mentioned by pilot
- Witness had been on helicopters several times previously
- Witness wasn't aware of pilot attempting or executing any emergency procedures
- "Kind of a shaky site to try and land on"
- Landing site ground was sloped
- "Came in forward, bumped, then started spinning"