



RECORD OF CONVERSATION

Albert P. Nixon
Aviation Accident Investigator
Western Pacific Region

Date: January 21, 2013
Person Contacted: Rob Wolfley (Garkane Energy, Garfield Area Manager)
NTSB Accident Number: WPR13FA095

Narrative:

During a conversation with Rob Wolfley, he stated:

- The power line between Escalante and Bolder experienced a power disruption at 3.01 pm.
- He responded to the area of the power outage and noticed power lines near mile marker 78 on Utah State route 12 were tangled.
- First responders told him that a portion of the airplane's wing was lying on the road and it was necessary to move off the road.
- Two power line poles were damaged and the attached power lines were lying near the ground.
- His personnel measured the approximate point of impact on the wires to be about 100 feet above ground level.