



NATIONAL TRANSPORTATION SAFETY BOARD

Eastern Region – Ashburn, Virginia

RECORD OF CONVERSATION

Who: John Wilczak, FAA A&P mechanic

When: July 24, 2017

RE: ERA17FA226

In a telephone conversation, Mr. Wilczak stated that the pilot/owner of N45851, Jon Coxwell, had purchased two seatbelt/shoulder harness assemblies to be installed in the airplane. He said the assemblies were part of an STC, but he could not recall who owned the STC or from whom he had purchased them. Mr. Wilczak stated that he had just installed a new fuel selector valve and the plan was to install the new seatbelt/shoulder harnesses assemblies next.

Leah D. Read
Sr. Air Safety Investigator
National Transportation Safety Board