



## **RECORD OF E-MAIL CORRESPONDENCE**

**Eric M. Gutierrez**  
**Aviation Accident Investigator**  
**Eastern Region Area**

---

**Date: February 20, 2020**  
**Person Contacted: Randy Ryhal (FAA)**  
**NTSB Accident Number: ERA20CA106**

---

### **Narrative:**

The following is a synopsis of the information provided by Mr. Ryhal in an e-mail correspondence.

An FAA inspector over saw the inspection of N188FS, an Airbus helicopter, AS350B2, with participation from the Hillsboro County Sheriff Office (HSCO) maintenance personnel and Airbus engineering. They identified the area of attachment for the Left Hand anti-vibrator mount beam (structural) was damaged.