



## **RECORD OF PHONE CONVERSATION**

**Eric M. Gutierrez**  
**Aviation Accident Investigator**  
**General Aviation Accident Division**

---

**Date: November 6, 2019**  
**Person Contacted: Robert Person (Pilot)**  
**NTSB Accident Number: GAA20CA059**

---

### **Narrative:**

The following is a synopsis of the information provided by Mr. Person in a telephone conversation.

On 3 November 2019, while landing on a private grass strip about sunset, near Greer, SC., as he came over the trees, he was surprised by a sudden inability to see the runway. This resulted in a late flare, the airplane bounced and drifted left. The airplanes left main landing gear touched down in the tall grass adjacent to the runway. The airplane continued to veer left and impacted a fence. He was unsure what caused the sudden inability to see the runway.

Total time: approx. 121

Make and Model: approx. 100