



Washington Gas

ODORANT MONITORING SAMPLE

Version: Effective 3/1/2015

JURISDICTION OF SAMPLE: DC VA MD

TECHNICIAN'S STATION: S.E N.W S.O.C FREDERICK SHENANDOAH N/A - CONTRACTOR

Reason for Sampling

- Fixed Point Random Sample Farm Tap
- Incident Low Odor Follow Up New Business

Sampled By

WG - Emp. No. 10400 TONY / 7705 TED
 Contractor - Badge No. _____

Odorator Serial Number: 2307-4

Name: [REDACTED] Date of LAST Odorator Calibration: 4-8-16

No.	ODORANT SAMPLING POINT	Odor Recognition			Analysis
		Quad Map, Address or Intersection, City, State	Date	Inst. Read	%GIA
1	Quad: <u>8609 PINEY BRANCH RD - SILVER SPRING MD.</u>	<u>8-11-2016</u> <u>3:45 AM</u>	<u>.60</u>	<u>.50</u>	
2	Quad				
3	Quad				
4	Quad				
5	Quad				
6	Quad				

****Notes:**

Procedures:

Contact Operations Dispatch [REDACTED] if the %GIA is greater than 1.0 for samples taken in VA or DC or greater than 0.5 for MD. All low odor conditions should be reported to Operations Dispatch.

Procedure: Reference WG O&M Manual Standards Section 4114 for ALL CLARIFICATIONS

Return these forms by company mail to the "Odorant Monitoring Program" or by fax to [REDACTED]

Reviewed by: [REDACTED] Date: 08-11-2016



Washington
Gas

ODORANT MONITORING SAMPLE

Version: Effective 3/1/2015

JURISDICTION OF SAMPLE: DC VA MD

TECHNICIAN'S STATION: S.E N.W S.O.C FREDERICK SHENANDOAH N/A - CONTRACTOR

Reason for Sampling

- Fixed Point Random Sample Farm Tap
 Incident Low Odor Follow Up New Business

Sampled By

- WG - Emp. No. 7705
 Contractor - Badge No. _____

Odorator Serial Number: 2307-4

Name: [REDACTED]

Date of LAST Odorator Calibration: 4-8-2016

No.	ODORANT SAMPLING POINT	Odor Recognition			Analysis
		Quad Map, Address or Intersection, City, State	Date	Inst. Read	%GIA
1	Quad UNIVERSITY BLVD & COLESVILLE RD.	8-11-2016 11:05 AM	.60	.50	REG STATION 424
2	Quad UNIVERSITY BLVD & SEEK LN.	8-11-2016 11:20 AM	.60	.50	REG STATION 447
3	Quad BOTH IN				
4	Quad SILVER SPRING MD.				
5	Quad				
6	Quad				

****Notes:**

Procedures:

Contact Operations Dispatch [REDACTED] if the %GIA is greater than 1.0 for samples taken in VA or DC or greater than 0.5 for MD. All low odor conditions should be reported to Operations Dispatch.

Procedure: Reference WG O&M Manual Standards Section 4114 for ALL CLARIFICATIONS

Return these forms by company mail to the "Odorant Monitoring Program" or by fax to [REDACTED]

Reviewed by [REDACTED]

Date: 8-11-16