NATIONAL TRANSPORTATION SAFETY BOARD

RD ACCIDENT NUMBER:

RETENTION / RELEASE OF WRECKAGE RELATED TO ACCIDENT NUMBER ►

ENG11IA051

For Use In All Modal Investigations				
REGISTERED OWNER (name and address)			IDENTIFICATION NUMBER	
United Air Lines				
233 South Wacker Drive			МАКЕ	
Chicago IL 60606			Boeing	
LOCATION DATE OF ACCIDENT			MODEL	
Denver International Airport	9/26/11		757-222	
RETAINED BY NTSB REPRESENTATIVE		TITLI		DATE
Jean-Pierre Scarfo		Pow	werplant Lead 9/29/11	
The National Transportation Safety Board has has not 🛛 completed its investigation of the wreckage described above. All recovered wreckage except that listed in the evidence control form(s) is hereby released.				
□ NO PARTS RETAINED				
RELEASED BY NTSB REPRESENTATIVE		TITLI	TLE DATE	
Jean-Pierre Scarfo		Pow	erplant Lead	9/29/11
(This section may be acknowledged by a person, not the owner or owner's representative, who has knowledge of the disposition of the recovered wreckage and its parts. Such acknowledgement does not place responsibility for disposition of the wreckage upon that person.)				
I HEREBY ACKNOWLEDGE:				
Receipt of the above described wreckage.				
Removal of the parts, if any, listed in the evidence control form(s).				
PERSON MAKING ACKNOWLEDGEMENT		TITLI	E	DATE
Pat Donahue Masters		Unit	ed Air Safety Investigator	9/29/11
ADDRESS		PHONE NUMBER & EMAIL		
		872	872 825-5618//Pat.Donahue@United.com	
REMARKS:				
Boeing 757-222 Registration Number N526UA is herby released back to United Air Lines except for Engine PW2037, SN P727118. The engine will be secured by United Air Lines at their Engine Repair Facility in San Fracisco, California until which time the Powerplant Group determines the final workscope and disposition of the engine.				
FDR - AlliedSignal PN 980-4700-042, SN 6252				