NATIONAL TRANSPORTATION SAFETY BOARD

ACCIDENT NUMBER:

RETENTION / RELEASE OF WRECKAGE RELATED TO ACCIDENT NUMBER ▶

CEN13LA462

For Use In All Modal Investigations					
REGISTERED OWNER (name and address)			IDENTIFICATION NUMBER		
FLIGHT OPTIONS LLC			N327FL		
CURTISS WRIGHT PKWY CLEVELAND, OH 44143			MAKE		
			EMBRAER S.A.		
LOCATION	DATE OF ACCIDENT	MODEL			
Eden Prairie, MN	8/5/13		EMB-505		
RETAINED BY NTSB REPRESENTATIVE		TITL	E DATE		
Thomas J. Latson, Jr.		Air	Safety Investigator 8/6/13		
The National Transportation Safety Board has \(\square\) has not \(\square\) completed its investigation of the wreckage described above. All recovered wreckage except that listed in the evidence control form(s) is hereby released.					
☐ NO PARTS RETAINED					
RELEASED BY NTSB REPRESENTATIVE		TITL	Ē	DATE	
Thomas J. Latson, Jr.		Air S	Safety Investigator	4/21/16	
(This section may be acknowledged by a person, not the owner or owner's representative, who has knowledge of the disposition of the recovered wreckage and its parts. Such acknowledgement does not place responsibility for disposition of the wreckage upon that person.)					
I HEREBY ACKNOWLEDGE:					
Receipt of the above described wreckage.					
Removal of the parts, if any, listed in the evidence control form(s).					
PERSON MAKING ACKNOWLEDGEMENT		TITLE		DATE	
TODD ANGUISH		FIL	GHT SHEETY MANAGED	ADR 26 2011	
ADDRESS		FLIGHT SAFETY MANAGER APR 26,2016 PHONE NUMBER & EMAIL			
CURTISS WRIGHT	PKWY CLE, OH				
REMARKS:					
The Cockpit Voice Data Recorder (CVDR) L3 Model FA2100, p/n 2100-3985-50, s/n 000611099 has					
been retained and will be returned when the NTSB Factual report is published:					
All other wreckage is released. The following parts which had previously been retained have since been					

All other wreckage is released. The following parts which had previously been retained have since been returned to the aircraft owner:

- 1. Brake Control Unit BCU p/n DAP00100-09 s/n 230000159 mod 1 was returned to the aircraft owner on 11/25/2015 via FedEx tracking number 513948160365
- 2. 3 SD Cards GDU10XX SUPPL DATA 010-00330-43 (marked: 1 and M and 2) have been returned to the aircraft owner

(end)