Jul 06 2018 14:45:38 Via Fax

Tactical Digital Cor Page 002 Of 005

ACCIDENT NUMBER: NATIONAL TRANSPORTATION SAFETY BOARD RETENTION / RELEASE OF WRECKAGE RELATED TO ACCIDENT NUMBER ▶ **ERA17FA317**

For Use in All Model Investigations REGISTERED OWNER (name and address) IDENTIFICATION NUMBER Herlihy Helicopters 204HF Medford NJ 08055 MAKE Schweizer LOCATION DATE OF ACCIDENT MODEL Medford NJ 9/8/17 269C RETAINED BY NTSB REPRESENTATIVE DATE TITLE ASI 7/6/18 Brian C. Rayner The National Transportation Safety Board has 🔯 has not 🗀 completed its investigation of the wreckage described above. All recovered wreckage except that listed in the evidence control form(s) is hereby released. NO PARTS RETAINED RELEASED BY NTS8 REPRESENTATIVE DATE TITLE Brian C. Rayner ASI 7/6/2018 (This section may be acknowledged by a person, not the owner or owner's representative, who has knowledge of the disposition of the recovered wreckage and its parts. Such acknowledgement does not place responsibility for disposition of the wreckage upon that person.) THEREBY ACKNOWLEDGE: Receipt of the above described wreckage. Removal of the parts, if any, listed in the evidence control form(s), PERSON MAKING ACKNOWLEDGEMENT TITLE DATE 7/6/18 J.J. Anglin President ADDRESS PHONE NUMBER & EMAIL Clayton DE REMARKS: Parts returned to Anglin Aircraft Recover Services 11/28/2017 by UPS (See Attached).



NATIONAL TRANSPORTATION SAFETY BOARD

MATERIALS LABORATORY DIVISION RECEIPT OF RETURNED PARTS

ACCIDENT/INCIDENT IDENTIFICATION								
PLA	ACE:	Medford, NJ						
DATE / VEHIC	CLE:	9/8/2017 Schweizer 269C1, N204HF						
NTSB NO. /	/ IIC:	ERA17FA317	Brian Rayner, AS-ERA					
THE FOLLOWING PARTS, PIECES OR COMPONENTS, FROM THE ABOVE ACCIDENT/INCIDENT								
Collective Throttle Control Assembly Throttle Cable, Linkage bell crank and Carburetor. Tie rod, rod in two pieces plus rod end bearing Box 39x39x6 26 lbs								
		ARE BEING RETURNED BY (1ZA4E7150392501273					
		WITH TRACKING	UPS Ground					
WHICH HAS BEEN ADDRESSED TO:								
NAME:	JJ	Anglin						
COMPANY:	An	glin Aircraft Recovery	Mary-					
ADDRESS:	Cla	yton, DE 19938						
TELEPHONE:								

RECIPIENTS PLEASE VERIFY THAT THE COMPONENTS, AS ITEMIZED, HAVE BEEN RECEIVED BY PRINTING YOUR NAME, SIGNING, AND DATING THIS FORM BELOW, AND RETURNING THIS DOCUMENT TO:


Mike Budinski, CHIEF, MATERIALS LABORATORY DIVISION, (RE-30) NATIONAL TRANSPORTATION SAFETY BOARD 490 L'ENFANT PLAZA EAST, SW WASHINGTON, DC 20594.

ATTACHED IS A SELF-ADDRESSED, STAMPED ENVELOPE FOR YOUR CONVENIENCE.

IF ANY DISCREPANCIES ARE FOUND, IMMEDIATELY CALL (202) 314-6530.

WRITER'S NAME AND INITIALS	Epperson			11/21/2017
NTSB REPRESENTATIVE PACKING PARTS	Epperson		DATE	11/21/2017
NAME AND SIGNATURE OF RECIPIENT OR RECIPIENT'S REPRESENTATIVE	Print	Sign	DATE	

Part Return Form (Word Template 08/17)





ATTN: BRIAN RAYNER

PHONE :

DELIVERY NOTIFICATION

INQUIRY FROM: BRIAN DENNIS

NTSB-DC

490 SW L'ENFANT PLAZA EAST SOU

WASHINGTON DC 20594

SHIPMENT TO: BRIAN RAYNER

CLAYTON DE 19938

According to our records, 1 parcel was delivered on 11/28/17 at 5:08 P.M., and left in your CUSTOMER'S GARAGE.