NATIONAL TRANSPORTATION SAFETY BOARD RELEASE OF AIRCRAFT WRECKAGE

ACCIDENT IDENTIFICATION
NUMBER
ERA10FA150

PART I-RELEASE OF AIRCRAFT WRECKAG

	PARTI-HELEA	9¢ OL VECTIV	IF! WHECKAGE		
REGISTERED OWNER (name and address) Skyway Leasing, Inc. 1802 N. Carson St., Ste. 212			REGISTRATION NUMBER—N		
			180ED		
Carson City, Nevada 89701-1230			MAKE	•	
			Be	eech .	
MODEL	DATE OF ACCIDENT	DATE OF ACCIDENT		LOCATION	
C23	February 25, 201	10	Winter Haven, Florida		
	e aide is hereby released to the r		stigation of the sircraft wreckage d er, or owner's repr esen tative, for		
SIGNATURE OF NTSB REPRESE	ENTATIVE	TITLE		DATE	
		Senio	r Air Safety Investigator	March 1, 2010	
			· · · · · · · · · · · · · · · · · · ·		
(This section may be signed by a	person, not the owner or owner	's representat	ive, who has knowledge of the dis	position of the aircraft wreck-	
age and its parts. Such signatur	e does not place a responsibility	for disposition	of the wreckage upon that person	ŋ	
HEREBY ACKNOWLEDGE:	•				
Receipt of the above describ	ed sircraft wreckage.				
Removal of the parts, if any,	, listed on the reverse side of this	form.			
SIGNATURE		TITLE		DATE	
		5	Cregional Claim Phoenix Arab	· ·	
X		X	Phoen ix Aval	X3/3/10	
REMARKS:				\	
		•			
		-			
				;	
-				. 1	

ACCIDENT IDENTIFICATION NATIONAL TRANSPORTATION SAFETY BOARD NUMBER RECEIPT OF AIRCRAFT PARTS

ERA10FA150

PART II-RELEASE OF AIRCRAFT PARTS

REGISTRATION NUMBER C23 180ED Beech DATE OF ACCIDENT LOCATION Winter Haven, Florida February 25, 2010

The National Transportation Safety Board has retained, for further examination, those parts, piaces, or components listed below. When the examination is complete, they will be returned to:

OWNER OR OWNER'S REPRESENTATIVE-

Adam Royse

ADDRESS

Phoenix Aviation Managers, Inc. 3501-B N. Ponce de Leon Blvd., # 236

St. Augustine, Florida 32084 Work Phone: (904) 687-0132

PARTS, PIECES, OR COMPONENTS RETAINED:

- 1. Garmin nuvi 250W, S/N 15B131901.
- 2. Pilot Logbook (James Trefz).
- 3. Fuel selector valve with attached handle, plastic shroud, and steel guide.
- 4. Section of throttle cable.
- 5. Left Magneto Teledyne Continental Motors Type S4LSC-21, P/N 10-500514-1, S/N D06JAJ02.
- 6. Right Magneto Teledyne Continental Motors Type S4LSC-21, P/N 10-500514-1, S/N D06JAJ01.

SIGNATURE OF NTSB REPRESENTATIVE	TITLE	DATE
	Senior Air Safety Investigator	March 1, 2010
		<u> </u>

The registered owner or owner's representative will acknowledge receipt of the materials by signing this form in the spaces designated below.

SIGNATURE OF OWNER OR OWNER'S REPRESENTATIVE

ADDRESS

SE Regional Claims 10/27/10

× Rep &