



<b>National Transportation Safety Board</b> RECEIPT OF AIRCRAFT PARTS	ACCIDENT IDENTIFICATION NUMBER CEN12LA151
--	--

**PART II -- RELEASE OF AIRCRAFT PARTS**


REGISTRATION NUMBER  N31WS	MAKE  Gates	MODEL  Learjet 35
DATE OF ACCIDENT  2/2/2012	LOCATION  Pueblo, CO	

The National Transportation Safety Board has retained, for further examination, those parts, pieces, or components listed below. When the examination is complete, they will be returned to:



**OWNER OR OWNER'S REPRESENTATIVE --** Travel Air Services (operator)  
  
**ADDRESS**

**PARTS, PIECES, OR COMPONENTS RETAINED:**

Garmin GPSmap 496  
RH MLG tires (2)  
RH MLG broken section of torque link

SIGNATURE OF NTSB REPRESENTATIVE 	TITLE  SR. ASI	DATE  Feb 23, 2012
---	----------------------	--------------------------

The registered owner or owner's representative will acknowledge receipt of the material by signing this form in the spaces designated below.

SIGNATURE OF OWNER OR OWNER'S REPRESENTATIVE 	TITLE  Director, Aviation Claims	DATE  12.5.12
ADDRESS  Englewood, CO 80112		