

## **Aguilera Jason**

---

**From:** James Baldwin [REDACTED]  
**Sent:** Friday, June 03, 2016 11:45 AM  
**To:** Aguilera Jason  
**Subject:** N443JF accident report

In regard to the accident involving N443JF I do not believe that the engine control cables proximity to the left rudder pedal had anything to do with the loss of engine power. James Baldwin [REDACTED]