



SR22-G2 QUICK REFERENCE  
**CHECKLIST**





**DESCENT**

1. Altimeter ..... SET
2. Cabin Heat/Defrost ..... AS REQUIRED
3. Fuel System ..... CHECK
4. Mixture ..... AS REQUIRED
5. Flaps ..... AS REQUIRED
6. Brake Pressure ..... CHECK

**BEFORE LANDING**

1. Seat Belts & Shoulder Harness ..... SECURE
2. Mixture ..... FULL RICH
3. Fuel Pump ..... BOOST
4. Flaps ..... AS REQUIRED
5. Landing Light ..... AS REQUIRED
6. Autopilot ..... DISENGAGE

**BALKED LANDING/GO-AROUND**

1. Autopilot ..... DISENGAGE
  2. Power Lever ..... FULL FORWARD
  3. Flaps ..... 50%
  4. Airspeed ..... 75-80 KIAS
- After clear of obstacles:*
5. Flaps ..... UP (0%)

**AFTER LANDING**

1. Flaps ..... UP
2. Power Lever ..... 1000 RPM
3. Transponder ..... STBY
4. Pitot Heat ..... OFF
5. Fuel Pump ..... OFF

**SHUTDOWN**

1. Avionics Switch ..... OFF
2. Fuel Pump ..... OFF
3. Mixture ..... CUTOFF
4. Magnetos ..... OFF
5. Bat-Alt Master Switches ..... OFF
6. ELT ..... TRANSMIT LIGHT OUT
7. Chocks, Tie-downs, Pitot Covers ..... AS REQUIRED