

DCA-13-MR-002  
Derailment/Hazardous Materials Release  
Paulsboro, NJ  
November 30, 2012

## ATTACHMENT 4

FRA Inspection 71CRSH 8 3 2012

# INSPECTION REPORT

Inspector's Name Noon, Thomas		Inspector's Signature			Inspector's ID No. 65250	Report No. 71	Date yy mm dd 2011 08 03		
Railroad/Company Name & Address CONSOLIDATED RAIL CORP. Consolidated Rail Corporation Woodbury Heights NJ 08097				R/C R	Division SYSTEM	RR/Co. Representative (Receipt Acknowledged) Name Kris Kneib Title signal supervisor south Jersey Signature _____			
From: City PENNSVILLE		Codes 2565	Destination City & County			Codes	From Latitude		
State NJ		34	City				From Longitude		
County SALEM		C033	County				To Latitude		
Mile Post: From 0013.00 To 0014.00			Inspection Point PAULSBURRO BRIDGE			To Longitude			
Activity Code:	INTO	RWP	HGCS	HGCO					
Units:	2	1	4	3					

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1	0020.00			234	0217	06			585979H	N	N	1	HGCS

Description  
FLASHING LIGHTS DO NOT FLASH ALTERNATELY. one light out Bridge port road

Violation Recommended  Yes  No Latitude: Longitude:

Written Notification to FRA of Remedial Action is:  Required  Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
2	0020.00			234	0217	01	30		585979H	N	N	1	HGCS

Description  
FLASHING LIGHT NOT VISIBLE TO APPROACHING HIGHWAY USER. lights out of focus

Violation Recommended  Yes  No Latitude: Longitude:

Written Notification to FRA of Remedial Action is:  Required  Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?