DCA-13-MR-002 Derailment/Hazardous Materials Release Paulsboro, NJ November 30, 2012

ATTACHMENT 7

Service Desk Event Log

24 Events

Location Name Broblem Time Reported Pallure Could Cleared Time Cleared Time Cleared Time Cleared Time Cleared Time Crew reports bridge was on when they arrived. Invest of the provided in the particular of the provided in the provided in the particular of t	
when they arrived. Crew re will not open or close. Info Spvr Ohr reports debris wa bridge. B&B Dept removed closed bridge. B&B Dept removed closed bridge is loc for season. 1:33 12/1/2011 BRIDGE REMOVE DEBRIS DEBRIS 2:42 12/1/2011 for season. Informed Supervisor Kneib maintainer is in the area per Kneib. Mtr Duross has no of Kneib.	
Maintainer is in the area per ADJUSTED NORTH PROX- Kneib. Mtr Duross has no o	eports bridge ormed Spvr Ohr. as stuck in d debris, and
	er Supervisor
60120 PAULSBORO BRIDGE WILL NOT CLOSE 8:21 3/27/2012 BRIDGE NONE / TESTED UNKNOWN / COA 5:02:31 PM 3/27/2012 Informed Mtr Devlin and So Spyr Ohr bridge closed and arrival. Spyr Ohr tested brid not duplicate problem. Brid intended with no exception	l locked upon dge and could dge working as
Per Mtr Devlin: replacing a 60162 PAULSBORO BRIDGE STOP SIGNALS 8:39 4/3/2012 SENSORS REPLACE DEFECTIVE 10:00:00 AM 4/3/2012 sw (PR1)	defective prox
CO20C DATH CDODG DRIDGE DRIDGE WILL NOT ODEN 4/3/2012 SW (FB.).	OPPORT OF THE PROPERTY OF THE
PAULSBORO BRIDGE WILL NOT OPEN 16:44 4/22/2012 BRIDGE WILL NOT OPEN TIGHTEN MITRE RAILS VIBRATION 7:47:54 PM 4/22/2012 Informed Supervisor Kneib REMOVE BRANCH FROM RAIL	*20**Mortal Charles of the section o
60334 PAULSBORO BRIDGE WILL NOT DROP 8:40 4/25/2012 BRIDGE SEAT UNDER INVESTIGATION 11:00:00 AM 4/25/2012 Spvr Vant sending Mtr.	
HAVE A STOP SIGNAL INDICATION WHEN BRIDGE IS SHOWING LOCK 15:27 7/5/2012 SHOWING LOCK REPLACE PD # DETECTOR BAD PD # DETECTOR 5:41:50 PM 7/5/2012 Informed supervisor Vant	
Supv K.Knieb informed. // F there was a Red signal. Mt PAULSBORO BRIDGE NO SIGNAL SOUTH BOUND 5:07 7/10/2012 TRACK CIRCUIT ADJUST THE PROX SWITCHS RAIL SHIFTED 7:30:00 AM 7/10/2012 North prox switches due to	r adjusted the
SUPV NOTIFIED:MNTR ADJUSTED # 3 & # 4 PROX DETECTORS ON THE IDENTIFY DETECTORS ADJUSTED # 3 & # 4 PROX DETECTORS ON THE IDENTIFY DETECTORS BRIDGE DUE TO RAIL SHRING DETECTORS ADJUSTED # 3 & # 4 PROX DETECTORS ON THE IDENTIFY DETECTORS BRIDGE DUE TO RAIL SHRING DETECTORS ADJUSTED # 3 & # 4 PROX DETECTORS ON THE IDENTIFY DETECTOR OF THE IDENTIFY DETECTOR	NORTH SIDE OF
61777 PAULSBORO BRIDGE NO SIGNAL SOUTH 6:33 9/11/2012 COA NONE UNDER INVESTIGATION 10:00:00 AM 9/11/2012 Tested, no exceptions found	und COA.
Supv K.Kneib informed. // In Devlin. Per Mtr: adjusted the DETECTORS 3 & 4 RAIL SHIFTING 8:28:00 AM 9/17/2012 detectors due to rail shifting CLEARED ERROR TESTED.	he 3 & 4 prox
CLEARED ERROR, TESTED 62368 PAULSBORO BRIDGE BRIDGE FAILED TO OPEN 9:00 10/27/2012 BRIDGE FAILED TO OPEN (NORTH-RAIL LINK) UNKNOWN 11:30:00 AM 10/27/2012	

Name Location Name	Problem	Time Penorted	Date Reported	Fallure					
62528 PAULSBORO BRIDGE	THE BRIDGE WILL NOT LOCK			THE BRIDGE WILL NOT LOCK	REMOVE DEBRIS FROM THE SEAT AND THE GEARS	Cause DEBRIS	Cleared Time 5:45:22 PM	Cleared Date 10/31/2012	Per Supervisor Ohr the maintainers removed the debris from from the seat and also remove debris from the gears which control the seat.
62587 PAULSBORO BRIDGE	BRIDGE ANNOUNCING FAILURE TO OPERATE	1:21	11/3/2012	BRIDGE	NONE / OPEN IN LOCAL CONTROL	UNKNOWN	6:58:18 AM	11/3/2012	Crew reports bridge is down and locked and signal is displayed, but announcement is reporting a closure failure. Informed Spvr Hill. Informed Spvr Vant, hold for AM. Next train reported stop signals at bridge, train talked by stop signal by Dispatcher. 05
62619 PAULSBORO BRIDGE	BRIDGE WILL NOT OPEN	15:59	11/5/2012	BRIDGE	ADJUST PROX DETECTOR	UNDER INVESTIGATION	6:32:38 PM		Informed by Spvr Ohr. Insp Greiner found the north side rail pumping under train moves causing the prox detector to break contact. Insp adjusted prox switch on the north side of the bridge and tested.
62644 PAULSBORO BRIDGE	BRIDGE WILL NOT OPEN	16:02	11/6/2012	BRIDGE	CLEAR ERROR CODE IN CONTROL PANEL	UNDER INVESTIGATION	5:39:42 PM		Crew reported to Dispatcher bridge announced "Failure to Operate." Informed Spvr Ohr, Per Spvr Spec Fitting will handle.Spec Fitting reported finding an error code on the control panel for Failure to Operate. Spec cleared error code and bridge opened. Spe
				į į			3.33.72 (10)	~~~~	Supvs K.Kneib & B&B Supv R.Hilll
62786 PAULSBORO BRIDGE 62792 PAULSBORO BRIDGE	NO SIGNAL NORTHBOUND BRIDGE FAILED TO CLOSE	23:15	11/16/2012	\$	NONE/OPERATED/TESTED	COA - NOTHING FOUND	12:00:00 AM	11/17/2012	
02/92 PAULSBURU BRIDGE	BRIDGE FAILED TO CLOSE	11:27	11/1//2012	BRIDGE FAILED TO CLOSE	RESET BRIDGE	UNKNOWN	2:47:03 PM	11/17/2012	RYAN HILL NOTIFIED:
62810 PAULSBORO BRIDGE	NO SIGNAL SOUTHBOUND	23:21	11/19/2012	NO SIGNAL SOUTHBOUND	RESET BRIDGE CIRCUIT	UNDER INVESTIGATION	1:03:00 AM		B&B Supv R.Hill informed. // PA21 crew reported bridge announced itself closed but got no signal. Crew walked the bridge and stated that the bridge is not locked.
				BRIDGE DID NOT OPEN AFTER		*			Crew reports bridge was closed upon arrival, but they did not have signal. Crew visually inspeced bridge and were talked by signal by Dispatcher. After train cleared bridge, bridge announced Failure to
62816 PAULSBORO BRIDGE	BRIDGE DID NOT OPEN AFTER TR		11/21/2012	A second transfer of the second secon	NONE (COA)	UNDER INVESTIGATION	3:40:16 PM	1	Operate. Informed Spvr Hill.
62854 PAULSBORO BRIDGE	BRIDGE FAILED TO LOCK	7:19	11/26/2012	BRIDGE FAILED TO LOCK	REMOVED DEBRIS	DEDRIS	12:30:00 PM	*******************************	RYAN HILL NOTIFIED:

Location Name	Problem	Time Reported	Date Reported	Failure	Repairs	Cause	Cleared Time	Cleared Date	Notes
62874 PAULSBORO BRIDGE	BULB OUT (DISTANT SIGNAL TO	E 7:52	11/28/2012	BULB OUT (DISTANT SIGNAL TO BRIDGE)	REPLACED BULB	BULB OUT	1:48:20 PM		DISP REPORTS A BULB OUT ON THE DISTANT SIGNAL TO PAULSBORO BRIDGE. (THE SIGNAL AT LEONARD ROAD-MP
62890 PAULSBORO BRIDGE	BRIDGE WILL NOT CLOSE	3:17	11/29/2012	BRIDGE	NONE / COA	UNDER INVESTIGATION	4:29:00 AM		Informed Spvr Hill. Train reports bridge was about 4 inches shy of being closed upon arrival. Crew reports bridge closed after several attempts, signal displayed but bridge did not announce. Train crossed bridge and bridge announced failure to operate. B&
62905 PAULSBORO BRIDGE	Derailment	7:05	11/30/2012	Derailment				V The "A Media Registrativa masser and the cell that and a monoral country and a global generally	APPROX 4 CARS FROM CA11 WENT INTO THE RIVER. NOTIFIED RYAN HILL AT 07:09