

NATIONAL TRANSPORTATION SAFETY BOARD
Vehicle Recorder Division
Washington, D.C. 20594

October 6, 2009

Sound Spectrum Study - 12 Errata

**Group Chairman's Report
by Joseph A. Gregor**

A. EVENT

Location: Columbia, SC
Date: September 19, 2008, 23:53 EDT
Aircraft: LearJet 60, N999LJ
Operator: Global
NTSB Number: DCA08MA098

The following items should be changed in the Sound Spectrum Study Report to correct a typographical error:

1. Page 12-2, paragraph 3, Sentence 6:

Change:

**Time zero in these figures corresponds to approximately
2354:32.2 EDT.**

To read:

**Time zero in these figures corresponds to approximately
2354:42.2 EDT.**

JOSEPH A. GREGOR
Vehicle Recorder Specialist