

APPENDIX J

AVJET CORPORATION WORK HISTORY

4301 Empire Avenue
Burbank, CA 91505
818-841-6190 • 818-563-3180 Fax
Workorder No. 4015



AVJET CORPORATION
FAA Repair Station No. ABFR012C
March, 2001

Aircraft Model: Gulfstream III
Aircraft Serial No: 303
Aircraft Registration No. N303GA
Page 1 of 1

03/01/01 Hours: 7258.0 Landings: 3499

1. Complied with CMP Codes 241402, 262530, 262532, 263051, 263052.
2. Complied with CMP Codes 241401, 241402. #1 and #2 Ni-Cad Battery Deep Cycle. Removed and replaced #1 and #2 Main Batteries with Deep Cycled Units from Aviall, Inc. #1 Battery P/N Off: 24535-010 S/N Off: 9801163; P/N On: 34535-010, S/N On: 9801163; #2 Battery P/N Off: 24535-010, S/N Off: 9805993; P/N On: 24535-010, S/N On: 9805993.

This certifies that only the work performed as described on our work order listed below was accomplished and inspected in accordance with manufacturer's specifications and with current Federal Aviation Administration regulations, and is approved for return to service. Pertinent details of this repair are on file at this agency under Workorder 4015.

Signed:  for
Avjet Corporation, Repair Station No. ABFR012C
4301 Empire Avenue Burbank, CA 91505

03/28/01 Hours: 7265.7 Landings: 3507

1. Complied with Part-I of Alert Customer Bulletin [REDACTED]. Main Landing Gear Door Control Valves are N/A by Part Number. Part-II due in 50 landings, not to exceed three Months, for the Nose Landing Gear Door Control Valve - [REDACTED].

This certifies that only the work performed as described on our work order listed below was accomplished and inspected in accordance with manufacturer's specifications and with current Federal Aviation Administration regulations, and is approved for return to service. Pertinent details of this repair are on file at this agency under Workorder 3993.

Signed:  for
Avjet Corporation, Repair Station No. ABFR012C
4301 Empire Avenue Burbank, CA 91505

APPENDIX J

4301 Empire Avenue
Burbank, CA 91505
818-841-6190 • 818-563-3180 Fax
Workorder No. 3993



AVJET CORPORATION
FAA Repair Station No. ABFR012C
February, 2001

Aircraft Model: Gulfstream III
Aircraft Serial No: 303
Aircraft Registration No. N303GA
Page 1 of 1

J2/12/01 Hours: 7232.8 Landings: 3495

1. Removed and replaced Autopilot Computer with an overhauled unit, P/N OFF & ON 4029377-906, S/N OFF 80100198, S/N ON 80090179.

This certifies that only the work performed as described on our work order listed below was accomplished and inspected in accordance with manufacturer's specifications and with current Federal Aviation Administration regulations, and is approved for return to service. Pertinent details of this repair are on file at this agency under Workorder 3993.

Signed: John L. Bailey II for
Avjet Corporation, Repair Station No. ABFR012C
4301 Empire Avenue Burbank, CA 91505

02/22/01 Hours: 7258.0 Landings: 3499

1. Removed and replaced Cabin Temperature Control Valve with a repaired unit, P/N OFF & ON 397122-1-2, S/N OFF P-723, S/N ON P-837.

This certifies that only the work performed as described on our work order listed below was accomplished and inspected in accordance with manufacturer's specifications and with current Federal Aviation Administration regulations, and is approved for return to service. Pertinent details of this repair are on file at this agency under Workorder 3993.

Signed: John L. Bailey II for
Avjet Corporation, Repair Station No. ABFR012C
4301 Empire Avenue Burbank, CA 91505

APPENDIX J

4301 Empire Avenue
Burbank, CA 91505
818-841-6190 • 818-563-3180 Fax
Workorder No. 3972



AVJET CORPORATION
FAA Repair Station No. ABFR012C
January, 2001

Aircraft Model: Gulfstream III
Aircraft Serial No: 303
Aircraft Registration No. N303GA
Page 1 of 2

J1/05/01 Hours: 7204.0 Landings: 3488

1. Removed and replaced Attitude Indicator Battery with an overhauled unit, P/N OFF & ON PS-823B, S/N OFF G-1438, S/N ON 2578. Updated GAC CMP Codes 341053 & 341056.
2. Complied with GAC CMP Codes: 262530, 262532, 263051, 263052, 332025, 335027, & 349250.
3. Complied with GAC CMP Codes: 337057, 337058, 344250, 344255.
4. Removed and replaced #1 & #2 INU Batteries with repaired units, #1 P/N OFF & ON CA-154-7, S/N OFF 8701679, S/N ON 9900142; #2 P/N OFF & ON CA-154-7, S/N OFF 8701687, S/N ON 9805174.

This certifies that only the work performed as described on our work order listed below was accomplished and inspected in accordance with manufacturer's specifications and with current Federal Aviation Administration regulations, and is approved for return to service. Pertinent details of this repair are on file at this agency under Workorder 3972.

Signed: John L. Bentley II for
Avjet Corporation, Repair Station No. ABFR012C
4301 Empire Avenue Burbank, CA 91505

01/09/01 Hours: 7204.0 Landings: 3488

1. Complied with GAC CMP Codes: 337057, 337058, 344250, 344255.
Removed and replaced #1 & #2 INU Batteries with repaired units, #1 P/N OFF & ON CA-154-7, S/N OFF 8701679, S/N ON 9900142; #2 P/N OFF & ON CA-154-7, S/N OFF 8701687, S/N ON 9805174.

This certifies that only the work performed as described on our work order listed below was accomplished and inspected in accordance with manufacturer's specifications and with current Federal Aviation Administration regulations, and is approved for return to service. Pertinent details of this repair are on file at this agency under Workorder 3972.

Signed: John L. Bentley II for
Avjet Corporation, Repair Station No. ABFR012C
4301 Empire Avenue Burbank, CA 91505

01/11/01 Hours: 7204.0 Landings: 3488

1. Complied with GAC CMP Codes: 490500, 490505, 490506, 490510, 490515, 490520, 490525, 490526, 490530, 490535, 490540, 490550, 490555, 491040, & 491050.

This certifies that only the work performed as described on our work order listed below was accomplished and inspected in accordance with manufacturer's specifications and with current Federal Aviation Administration regulations, and is approved for return to service. Pertinent details of this repair are on file at this agency under Workorder 3972.

Signed: John L. Bentley II for
Avjet Corporation, Repair Station No. ABFR012C
4301 Empire Avenue Burbank, CA

APPENDIX J

01/17/01 Hours: 7204.0 Landings: 3488

1. Complied with GAC CMP Codes: 253030, 263106, 352540, 352545, 352550, 573010, 573015, 736510, 736515, 770520, & 770525.

This certifies that only the work performed as described on our work order listed below was accomplished and inspected in accordance with manufacturer's specifications and with current Federal Aviation Administration regulations, and is approved for return to service. Pertinent details of this repair are on file at this agency under Workorder 3972.

Signed: John L. Bailey II for
Avjet Corporation, Repair Station No. ABR012C
4301 Empire Avenue Burbank, CA

01/17/01 Hours: 7204.0 Landings: 3488

1. Accomplished Airworthiness Directive ~~730322~~, Master Caution Panel Mod. One time inspection; N/A to this Serial No.

This certifies that only the work performed as described on our work order listed below was accomplished and inspected in accordance with manufacturer's specifications and with current Federal Aviation Administration regulations, and is approved for return to service. Pertinent details of this repair are on file at this agency under Workorder 3972.

Signed: John L. Bailey II for
Avjet Corporation, Repair Station No. ABR012C
4301 Empire Avenue Burbank, CA

01/18/01 Hours: 7204.0 Landings: 3488

1. Removed and replaced Main Batteries with overhauled units, #1 P/N OFF & ON CA-154-2, S/N OFF 8707110S/N ON 8918168; #2 P/N OFF & ON CA-154-2, S/N OFF 9903445, S/N ON 8913206.
2. Removed and replaced Main Batteries with overhauled units, #1 P/N OFF & ON CA-154-2, S/N OFF 9900142, S/N ON 8701679; #2 P/N OFF & ON CA-154-2, S/N OFF 9801574, S/N ON 8701681.

This certifies that only the work performed as described on our work order listed below was accomplished and inspected in accordance with manufacturer's specifications and with current Federal Aviation Administration regulations, and is approved for return to service. Pertinent details of this repair are on file at this agency under Workorder 3972.

Signed: John L. Bailey II for
Avjet Corporation, Repair Station No. ABR012C
4301 Empire Avenue Burbank, CA

01/19/01 Hours: 7204.0 Landings: 3488

1. Complied with GAC CMP Codes: 770510 & 770515.

This certifies that only the work performed as described on our work order listed below was accomplished and inspected in accordance with manufacturer's specifications and with current Federal Aviation Administration regulations, and is approved for return to service. Pertinent details of this repair are on file at this agency under Workorder 3972.

Signed: John L. Bailey II for
Avjet Corporation, Repair Station No. ABR012C
4301 Empire Avenue Burbank, CA

APPENDIX J