

LOWER SKIN PANEL - WING CENTER TANK

CW-203

C-193

GREEN

This is a small piece that extends from LBL 12 to LBL 63 and from the rear spar to S-2. S-1 and S-2 are not attached and the rear spar lower chord remained attached. CW-1005 remained attached to this section at the rear spar.

The fwd outboard corner is bent down approx 5" with respect to the remainder of the section. The stiffener attached to the underside of the panel at LBL 57.5 has it's free flange buckled. There is only one rivet remaining in the panel at S-1 which exhibits shear failure outboard. The failure line at the fwd edge is through the fastener line at S-2. The holes at S-2 are elongated fore and aft.

The interior and exterior surfaces of this panel are sooted.

Wann Stewart 10/29/96 BOEING

J. S. GREEN 10/31/96 ALPA

Tom Todaro
FAA 11-4-96

R. M. Phillips 11-26-96 TWA

R. S. Smith 12-7-96 JAM