

LOWER SKIN PANEL - WING CENTER TANK

CW-233	CW-234
Z-2703	Z-2757
GREEN	GREEN

These are two small pieces of skin panel at the front spar near the right hand S.O.B. CW-233 has a portion of the lower skin flange of the spar chord attached and also one shear tie.

The fracture matches between the two parts and if mated together will form an s-shape with the lower spar chord deflected up on the outbd end. Both parts are heavily curled. The remainder of the rivets between the spar chord on the inbd section and the skin on the outbd section show shear failure and the remainder of the holes in CW-234 show elongation in the inbd/outbd direction.

The inner and outer surfaces of the sections are sooted except for the interface of the RBL 104 underwing stiffener (which is unattached) is unsooted. See the Fire and Explosion Group notes for further documentation.

Steph F. Klupchuk 12-6-96 TWA

Steph F. Klupchuk

FAA 12-06-96

R. Brachetti IAM 12-6-96

SD GREEN ALPA 12-6-96

Boeing 12/7/96