

CW-514

FRONT SPAR

A-459

RED

This is a small section of the front spar stiffener at RBL 49.60 and was connected to the CW-501 stiffener at RBL 49.60.

It is about 35" long and separated from the shear tie at the upper surface. This stiffener is bent 45 degrees to the right at 15" from the top. A 4" X 20" web piece is attached to the forward flange with all its rivets and is bent/curled forward on both sides at the forward stiffener flange.

See Fire & Explosion Group Notes for Documentation 10/24/96 JAM

~~There is no evidence of any fire damage to this part of the front spar.~~

AKenna 10/20/96
BOEING

SO GREEN 10/29/96

ALPA

R. Beach 10/30/96
JAM

Stephen F. Klapach Sr.
FAA 10-31-96 Nchato

J. M. Miller 11-26-96 TWA