

CW 638

Id No: 11-20-96-144

Tag No: X-4070 Red

Spanwise Beam 3 - RBL 83.2
Stiffener free flange

This segment includes the entire free flange
of the RBL 83.2 stiffener and approx
50% of the up standing leg. The
Part shows signs of salt water corrosion.

Steph F. Klappach - ALPA
3-21-97

Dennis Santiago IAM
4-2-97

STEPHEN F. KLAPPACH SR
FAA 09-03-97

Bhanderhude TWTZ 3/24/97

D. James
2/3/97