

WING CENTER SECTION - SPANWISE BEAM # 2

CW-706

B-2002

~~YELLOW~~ & white

This is a portion of the lower chord from BL 0 to LBL 25, a small portion of web, and a partial stiffener at LBL 9.

The remaining portion of web is a maximum of 20" tall and remains attached to the lower chord. Only 20" of the web attach flange of the LBL 9 stiffener still remains. Both the web and stiffener are bent fwd above the lower chord. The ^{upper} tension fitting at LBL 9 (keel beam attachment) remains attached to the lower chord and the hole common to the tension bolt is deformed/elongated in the lower chord on the aft side of the hole. The chord to skin panel fasteners that remain in the chord exhibit tensile failures.

See the fire and explosion group notes for documentation of soot accumulation.

Wayne Stewart 10/31/96 BOEING
Lawrence 11/1/96 FAA
SD GREEN 11/01/96 ALPA
W. M. 11-24-96 TWA
C. G. H. 11-25-96 IAM