

**NATIONAL TRANSPORTATION SAFETY BOARD**

Office of Aviation Safety  
Aviation Engineering Division  
Washington, DC 20594

May 16, 2001

**Errata to Structures Group Chairman's Factual Report**

**A. ACCIDENT: DCA99MA060**

**Location:** Little Rock Nat'l Airport (LIT), Little Rock, Arkansas

**Date:** June 1, 1999

**Time:** 2351 Central Daylight Time

**Airplane:** American Airlines Flight 1420, N215AA  
McDonnell Douglas DC-9-82 (MD-82)

**D. DETAILS OF THE INVESTIGATION**

**Section 2.5.2 Left Main Landing Gear, page 16.**

**Replace:** The inboard wheel brake housing was fractured and several pieces were missing.

**With:** The outboard wheel brake housing was fractured and several pieces were missing.

*K. M. Pudwill*  
[Redacted Signature]  
Kevin M. Pudwill  
Structures Group Chairman

*J. D. [unclear]*  
[Redacted Signature]  
J.D. [unclear]