

of the forward fuselage, left side. Note the extensive damage to the flooring and underlying airframe structure. Note that the first class seats on the left side are completely missing. (NTSB))