

forward and center fuselage sections. Note the crushing damage to the fuselage nose and the lighting system structure (i.e. angles) protruding from the fuselage near the forward galley service door.