



LOG # FBM-14

TARGET # \_\_\_\_\_

COORD: LAT \_\_\_\_\_

LONG \_\_\_\_\_

DEBRIS FIELD \_\_\_\_\_

14A NO TAG 12/4/96-4

14B NO TAG WITH GALLEY WIRES

14C - LLS 143

MISC STA 840 FLOOR BEAM  
PIECES

14A - UPPER CHORD RBL 31 TO RBL 60  
SEE F/B DWG. PORTION OF BLS4.49 S/T ATTACHED  
FRACTURED AT STA 839 AND 844

14B - LOWER CHORD LBL 70 TO LBL 96  
SEE F/B DWG

14C - UPPER CHORD AND WEB, LBL 21 TO  
LBL 33 SEE F/B DWG

Barry Sorensen  
10/23/96 BOEING  
You follow FAA  
10.25.96

Meeting  
10-22-96

[Signature]  
11-9-96

Dennis Santiago IAM  
11/23/96