



LOG # FBM-27

TARGET # \_\_\_\_\_  
 COORD: LAT \_\_\_\_\_  
 LONG \_\_\_\_\_

DEBRIS FIELD \_\_\_\_\_  
 27A NO TAG 8/10/96-9

FLOOR PANEL ASSORTMENT STA 700 TO STA 800 WITH FLOOR BEAM CHORDS ATTACHED.

27A STA 760 TO STA 770, LBL 76 TO LBL 99

F/P FRACTURED AT DECOMPRESSION VENT CUTOUT.  
 CONTAINS F/B UPPER CHORD @ STA 760

27B F/P # 89 FROM STA 760 TO 800, LBL 98 TO 117  
 PART 1 CUTOUTS FOR DECOMPRESSION PANELS. F/B UPPER CHORDS  
 & PART 2 FOR STA 760 & 780 FROM LBL 97 TO 117 ARE CONNECTED.  
 BL 98.56 S/C FROM STA 758 TO 800. FRACTURED @ 781 ALSO.

27C F/P # 75 FROM STA 680 TO STA 740  
 F/B 700 UPPER CHORD FROM LBL 73 TO LBL 94  
 F/B 740 UPPER CHORD FROM LBL 45 TO LBL 98  
 (SEE F/B DWG). FLR PNL EXTENDS TO STA 760, BTWN LBL 93 & 99

Dennis Santiago  
 IAM 11123198  
 11446

Bruce Smith  
 10/23/96 BRENG  
 Stephen F. Klupachon  
 10-25-96