



TARGET # _____
 COORD: LAT _____
 LONG _____

VARIOUS FLOOR BEAM
 PIECES (DWGS ARE IN F/B BOOK)

- DEBRIS FIELD TAG
- A) - Z 2742 GREEN
 - B) - NO ID AT ALL!
 - C) - 8/14/96-9 (RED)
 - D) 11/23/96-127 (RED)
 - E) 11/29/96-114 (RED)
 - F 1-13-97-85 N 708 (RED)
 - G SOURCE TAG A 190 (RED)
 - H 11-14-96-210 (RED)
 - I 1-13-97-46 red N 7064
 - J UN READABLE DATE SOURCE TAG A 540

- * A) ✓ FLOOR BEAM STA 960 RBL 101 TO TO SOB ON R/H SIDE. SEE F/B BOOK
- B) FLOOR BEAM STA 940, RBL 30 TO RBL 45 UPPER CHORD & WEB. SEAT TRACK ATTACHED, STA 917 TO STA 941 SEE F/B BOOK
- * C) ✓ F/B LOWER CHORD & WEB STA 920, LBL 5 TO LBL 30.
- * D) ✓ F/B UPPER CHORD STA 880, RBL 38 TO RBL 48
- * E) ✓ STA 880 FRAME C F/B UPPER CHORD ATTACHMENT. LBL 112 TO SOB, FRAME S-23 Q TO F/B LOWER CHORD FASTENERS. STRINGER CLIPS S-24, S25 & S 27 HAVE FASTENER TEAROUT & SHEAR TIE T'S HAVE BOTH FLANGES FRACTURE OFF @ FILLET RADIUS.
- * F) ✓ STA 900 F/B LOWER CHORD LBL 34 TO LBL 76
- * G) ✓ STA 900 F/B UPPER CHORD & RBL 33 99 AT INTERFACE
- * H) ✓ STA 880, LBL 74 TO LBL 80 F/B WEB & V CHANNEL
- * I) ✓ STA 960 F/B FROM LBL 42 TO LBL 73, WITH WEB & BOTH CHORDS ATTACHED
- * J) ✓ STA 960 F/B LOWER CHORD & V CHANNEL, LBL 76

Neil Stovell
 TWA 4-15-97
 PARTIAL SIGN OFF
 UNABLE TO LOCATE
 FBM 31-B
 Tom Tullman
 FAA 4-11-97
 ALL BUT
 FBM 31-B as
 found

NOTE: PARTIAL SIGN OFF
 ALPA 9A Request
 4/4/97
 ALL INT
 11/2/96
 (COULD NOT FIND/ID)

Chris Hartman IAM
 4-10-97 PARTIAL SIGNOFF
 FRM 31-B UNABLE TO LOCATE

B Smoot 1/18/97