


LOG # LF141  
 TAG # C2482  
 COORD: LAT \_\_\_\_\_  
 LONG \_\_\_\_\_

LONGITUDINAL FLOOR  
 BEAM LBL 33.99  
 STA 1295 - 1339

DEBRIS FIELD GREEN



THIS PART WAS ATTACHED TO RF 126 BY THIS SUPPLY LINE BUT FELL OFF.

• PART IS STRAIGHT EXCEPT FOR MOST FWD 10" WHICH IS BENT OUTBD 5" APPROX

1 VERTICAL LEG OF LWR CHORD ATTACHED STA 1315 - 1339

• PART IS MODERATELY SOOTED, BROKEN STIFFENER IS SOOTED

Dennis Santiago IAM  
 3-21-97

*Shirley...*  
 WFA 3/21/97

Tom Tidue -  
 FAR 3 28-97

Leigh D. J...-ASA  
 3-22-97

R. Hanauer  
 3/7/97