



LOG # LF 49 *PTA*

TARGET # _____

COORD: LAT ?

LONG ?

DEBRIS FIELD ?

REFER FIRE AND EXPLOSION GROUP NOTES FOR FIRE DAMAGE

THE SECTION IS APPROX 44 IN. HIGH AND 76 IN. ~~WIDE~~ WIDE AND RUNS FROM STATION 2484 BACK TO STA. 2552.4, ENCOMPASSING STRINGERS 44 UPWARD TO STR. 25.

THE SECTION IS ~~LOCATED~~ ^{LH} LOCATED DIRECTLY UNDER THE CUT-OUT FOR THE HORIZONTAL STABILIZER WHICH BEGINS AT STA. 2484. AT THE TOP, IT RUNS TO STA 2529 ALONG STR 23 THEN TORN TO STR 26. THE TEAR THEN RUNS ALONG STR 25 TO STA 2552.4 AND CONTINUES TO STR 42.

STNS. 24 AND 25 ARE CRUSHED, STR 26 IS MISSING, STR 36 IS MISSING FROM STA 2506 TO 2529, STR 38 IS BROKEN.

THE SECTION SHOWS NO SIGN OF FIRE OR SMOKE DAMAGE.

Jim Owens 11-6-96
Neil Scoville TWA 10-10-96
CF 7/10/23-96
Tom Todman FAA 8-25-96

