			///
		••	
0.0	The state of the s	Section Contraction	
- 4	ila el	<u> </u>	

LOG# LF54 A, BZC,

TARGET#

COORD: LAT

LONG

DEBRIS FIELD ?

LF 54A

REFER FIRE AND EXPLOSION GROUP NOTES FOR FIRE DAMAGE

THIS SECTION IS A HEAVY CHORD AND LONGERON AND MEASURES APPROX 4 FT X 5 FT AND ENCOMPASSES STA 1416 TWO 1480 AND STRINGERS S33L TWO SZBL; STRINGERS S31, S30, SZB ARE MISSING BETWEEN STA 1416 TO STA 1438. THE CHORD BEAM IS FRACTURED AT STA 1416. THERE IS NO SMOKE OR FIRE DAMAGE.

LF 54B (C-2389)

THIS "PIECE" MEASURES 2 FT X 1.FT AND ENCOM-PASSES STA 1460 BACK TO STA 1438, INCLUDES PORTIONS OF STR 891 WHICH / FRACTURED AND ROLLED OVER AT STA 1438. NO FIRE DAMAGE.

LF 54C (C-1017)

THIS SECTION MEASURES APPROX 3/2 FT X 1/2 FT AND ENGINPASSES STAS 1438 TO 1480 AND STRINGERS 28L THUR ZET. STRINGERS ARE FRACTURED AND MISSING FWD OF STA 1460.
NO FIRE DAMAGE JULY

LF 54D

THIS SECTION IS APPROX 3FT X 21/2 FT AND ENCOMPASSES STATION 1438 Thrm 1416 AND STRINGERS 26L Thrm 29L. THE PIECE IS SHEARED AND IRREGULAR IN SHAPE. STR 26L AND 29L ARE MISSING. STRINGERS 27L AND 28L ARE FRACTURED. NO FIRE OR SMOKE DAMAGE.

Meil Jordan Tom TODINO TWA JAM LOU FAA 8-26-96

Juin Powers Boeins 11-10-96

