


SEE ADDITIONAL COMMENTS



LOG # LF 83

CP 10/23/96

10-23-96

TARGET # \_\_\_\_\_

COORD: LAT \_\_\_\_\_

LONG \_\_\_\_\_

SKIN STA 1840 - 1880

S 27L TO S 32L

DEBRIS FIELD Green


Tag- 23225 (10-2-96)

REFER METALLURGY GROUP NOTES

FRACTURES AND APPEARANCE ARE LIKE LF 27C & D WHICH MATCH THE UPPER 1/2 OF LF 83 FRACTURE LINES

NO SMOKE OR FIRE DAMAGE

SMALL OUTWARD PUNCTURE @ STA 1862-1864, 1 INCH ABOVE S-32 - 1/2" WIDE BY 2" LONG (SOME SPIKE TOOTH APPEARANCE ON LOWER LIP OF PUNCTURE)




CJH - JAM  
10-27-96

Bony Smith  
10/8/96

Tom Tullino  
FMA 10-9-96

Neil Smith  
TWA - 10-17-96



cf file - IAM  
10-22-96

LF-83

- THERE IS A SECOND PUNCTURE AT  
THE TOP OF LF83 JUST BELOW  
S-28. <sup>→ & JUST AFT OF 1860 STA FRAME.</sup> IT MEASURES APPROX 2 3/4"  
LONG AND APPEARS TO BE ~~AT~~ FROM  
THE OUTSIDE GOING IN-

Rob Kanner - TBC  
12/5/96

Neil Scoville - TWA

12-5-96

Jon Zehner FAA

12-5-96

Dennis Santiago IAM

12-5-96