



ASSORTED SKINS

STA 1500 TO 1720  
\$ ~~32~~ TO \$41

DAMAGE TO PARTS  
ARE SIMILAR TO LF45  
AND LOWER END OF LF29

(SEE DIAGRAM FOR SIZE AND LOCATION)

LF88M HAS A BODY FRAME  
OUTER CHORD & SHEAR TIES  
IMPAIRED THRU @ STA 1600, \$32

LOG # LF88

TARGET # \_\_\_\_\_

COORD: LAT \_\_\_\_\_  
LONG \_\_\_\_\_

10/23/96

DEBRIS FIELD GREEN

LF88 A. Q-2434

B.V. Z-2846

C.V. Q-2442

O.A. A 2028 ✓ ?

E.V. NO TAG

F.V. 1

G.V. 1

H.V. Z 787 ✓

I.V. Z-2860

J.V. Z 3731

K.V. NO TAG

L.V. Q-2443

M.V. Z 3786

B Smoe Boeing

10/22/96

R. Bradley IAM

10/22/96

Smoking TWA

10-23-96

Tom Redwood  
FAX 10-23-96

