


Left T-wing



LOG # LW35

TARGET # _____

COORD Lat: _____

LONG: _____

Debris Field: C 222 GREENTAG

SEE ADDITIONAL COMMENTS

Pg 1 of 3

OUT BOARD SECTION OF THE
L/H INBD AILERON.

HEAVY SOOTING AND BURNING ON THE EDGES.

LOWER SIDE IS FACING UP. COMPOSIT PANELS ARE FRACTURED,
AND TRAILING EDGE OF AILERON IS MISSING. THIS
PIECE MEASURES APPROX 4X4 FT. APPEARS THAT MOST
OF THE DAMAGE WAS CAUSED BY ~~THE~~ ^{BY} TAREING AND IMPACT
~~IN THE~~

SD GREEN - ALPA

11-16-96

D. Santiago - IAM

11/7/96

- NTSB

Joe Zuber - FAA
10.28.96


PA. MALOTTE

FAA

R. ~~Star~~ - BOEING

T.M. ~~King~~ - TWA
10/13/96

Pg 2 of 3



AIRCRAFT CO.

LW 35
C 222 Green

See below FAA
10/28/96

TAC

2

LW 35 Additional Comments

Pg 3 of 3

~~IN~~ BOARD

1. ~~Inboard~~ rib has minimal to no sooting.

~~OUT~~ BOARD

2. ~~Outboard~~ rib web structure is burned away to some degree in all bays.

SD GREEN

ALIA

11-16-96

 - ALIA

12-6-96

~~Tom~~
TWA 12-6-96

Dennis Santiago IAM

12-6-96

Tom Todaro
FAA 12-6-96

D. Hill

BOEING 6 DEC 96