



LOG # RF113

AS
10/23/96

TARGET # _____

COORD: LAT 40 39 03

LONG 72 38 32

DEBRIS FIELD YELLOW

RF113A = B070

SKINS STA 434 TO STA 480

S-27A TO S-34R

A & B

FRACTURES ARE RANDOM THRU FASTENERS AND NOT
STA 460 SKIN SPLICE MISSING FROM S-31A TO
S-34 ALL STRINGERS ARE MISSING EXCEPT

S-28A, STA 470 - 480 SKIN SHOWS
SOME SLIGHT INWARD DIMPLE BETWEEN STRINGERS

Barry Smoot
10/22/96

Tom McKinnon
TWA 10/24-96

Dennis Houston IAM
10/28/96

Tom Tedlow
FAA 10-24-96

WL 194.225 (REF)

