

LOG # RF115

10-28-96

TARGET # \_\_\_\_\_

COORD: LAT \_\_\_\_\_

LONG \_\_\_\_\_

SKIN

STA 2340 - 2460 S-5-S17R

DEBRIS FIELD GREEN

TAG # Z3476

SKIN, STRIPPINGS AND SOME FRAME ATTACHED

SECTIONS

FRACTURED AROUND PERIMETER IS UNDER 50% T.H.P.U. FASTENER Q'S

LIGHT TO MODERATE SMOKE ON EXTERIOR WHERE PAINT IS STILL ADHERED

SOME CORROSION WHERE FINISH IS DETACHED.


NO SEVERE BENDS OR DENTS

Bobby Smith  
Boeing, 10/28/96

REFER FIRE AND EXPLOSION GROUP NOTES FOR FIRE DAMAGE

Dennis Lantieri IAM  
10-28-96

Tom Todman  
FAA 10-24-96  
McKinney  
TAM 10-18-96



S-12A  
 S-13A  
 S-14A  
 S-15A  
 S-16A  
 S-17A

CUTOUT FOR  
 HORIZONTAL STABILIZER

COE FIN FITTING ACTING AS LONGERON

2340

True To Dimensions  
 FAA 10-24-96

RF 115

DEVELOPED VIEW  
 RIGHT SIDE  
 1/10 SCALE

3