


RF 178
 LOT NO. 8-8-96-31
 WHITE

- NOTES:
1. LARGE PORTIONS OF HULL SECTION STRINGERS AND INTERCOSTAL REMAIN ATTACHED.
 2. BS 360 SKIN ATTACH FLANGES REMAINED ATTACHED.
 3. BS 370 FRAME SKIN ATTACH FLANGE REMAINS ATTACHED.



[Signature]
 9-12-97

Dennis Santoro
 IAM 9-12-97

[Signature]
 9-12-97

Tom Todaro
 FAA 9-12-97

S. CHISHOLM
 BOEING 9/24/97