


RF 183  
NO LOT NUMBER



- BS 300 FRAME SKIN ATTACH FLANGE REMAINS ATTACHED. (FRACTURED IN RADIUS.)
- S41R STRINGER SKIN ATTACH FLANGE REMAINS ATTACHED. (FRACTURED IN RADIUS.)

9-10-97  
TWA

9-11-97  
ALPA

Dennis Antrop IAM  
9-12-97

Tom Tochino  
FAA 9-11-97

S. Oskow  
Boeing