

no tag

LOG # RF 45 H
 TARGET #
 COORD: LAT
 LONG
 DEBRIS FIELD

Station 1800-1820

Piece measures 16" x 1 1/2"
 Master Latch Lock Handle (Handle in Full Stowed
 Position)

Skin bent out ward, cracked crushed
 complete Deformation.

See Attached sheet (Piece believed to belong to
 Recovery Area Green Field #1) Due to The
 Relationship to RF 45-A-B-C-D-E-F-G.)

09-18-96

S. Klapach
 FAA


Tom Todaro
 FAA 10-10-96

Henry Missel
 Boeing
 9-21-96

Tom Todaro
 TWA 10-10-96

14/15


25



MASTER LATCH LOCK MECHANISM

(A)

S. Klapach
FAA
9-18-96



MASTER LATCH LOCK HANDLE STOP

(B)

Master Latch Lock Mechanism
Figure 501 (Sheet 2)

15/15

EFFECTIVITY
ALL

52-34-00

02.1

3