RW-5

REFER FIRE AND EXPLOSION GROUP NOTES FOR FIRE DAMAGE

C232

RIGHT HAND WING LOWER SKIN PANEL

THE PIECE EXTENDS FROM WS 1196 TO WS 1364 AND FROM THE FRONT SPAR TO STRINGER 10, IT IS BUCKLED CHORDWISE BETWEEN WS 1196 AND WS 1280 WITH THE CENTER PUSHED UP RELATIVE TO THE FRONT SPAR AND STR 10.

STRINGERS 10,11,12, AND 13 REMAIN PARTIALLY ATTACHED TO SKIN BETWEEN WS 1224 AND WS 1300 (APPROX) WITH SOUTING VISIBLE ON THE UPPER HALF OF ALL 4-STRINGERS OVER ABOUT HALF THE LENGTH OF EACH,

SOUTING IS ALSO APPARENT ON THE FRAIT SPAR LOWER CHORD FROM WS 1252 TO WS 1280 ON THE HOFIZONIAL FLANGE, WHICH REMAINS ATTACHED TO THE SKIN, THE FRACTURE FACE ALSO IS SOUTED.

THE PANEZ OUTBO FROM WSIZBO REMAINS RELATIVELY FLAT. (SEE ALSO J. TRZIL NOTES, DATED 10/17/96 AND 10/19/96)

> D. URTH-BOEING 10/24/96

Stephen F. Klapault 7. FMA - 16 27-16

SO GREEN ALROY 11/03/86

Denis Senting I AM 11.26-96 Bed Sevell Tur

