



## SUMMARY for RECORD

Millicent Hill  
Air Safety Investigator  
Eastern Region Aviation

---

Date: February 12, 2020  
Person Contacted: Alberto Caraballo

---

This investigator made multiple attempts to contact Mr. Caraballo by telephone to obtain the NTSB Form 6120.1. Mr. Caraballo provided a statement to the Federal Aviation Administration inspector on December 22, 2019. He told them he did not have an email address and he spoke about the accident involving his Quicksilver MX II Sprint. He stated he was flying over the water and was trying to take a picture of himself and accidentally touched the fuel shut off valve, turning it to OFF. He ditched and was recovered by boaters. He stated the airplane logbook and his pilot logbook were in the airplane at the time of the accident and not recovered.