



SUMMARY OF FINDINGS

Tealeye Cornejo
Air Safety Investigator (Field)
Western Pacific Region

Date: December 6, 2019
Person Contacted: Ken Bradshaw Portland, OR FAA FSDO
NTSB Accident Number: WPR20CA041

Narrative:

N52458 Cessna 182P, departed Troutdale with 4 persons on board and about 69 Gallons of fuel. Student Pilot, Samuel V. Klets was flying and landed at Pearson. They departed Pearson and flew to Grove Field to land runway 25. The approach was normal, but the 182 seem to float on landing. The airplane touched down about mid-field and bounced. Instructor took controls asked for power and student pushed in throttle. According to the instructor, this occurred 2/3rds down the runway. The aircraft lifted off, but not enough altitude to clear fence. Aircraft continued across road and struck a second fence then landed in field. Student described winds as calm when they landed, but when I was on scene there was a slight breeze, and aircraft were departing runway 7.

No injuries to anyone on board. I spoke with CFI and Student; the two passengers had departed scene.

There is damage to the prop, and LH horizontal stab is twisted, a deep gouge on LH fuselage near cabin door, and there are some skin wrinkles back on the RH side of the tail below the horizontal stab

No reported mechanical issues.