Comair, Inc. Lexington, KY August 27, 2006 DCA06MA064

# NATIONAL TRANSPORTATION SAFETY BOARD WASHINGTON, D.C.

### ATTACHMENT 10

LEX OPERATIONS CENTER INCIDENT CAD REPORT

2 Pages

### Blue Grass Airport DPS Incident Report - 410

Alarm Date: 08/27/2006 06:05:00 AM Exposure: 0 Station: 34

NFIRS-1 Basic

Location

Census Tract: Location Type: Adjacent to

4478 Versailles Road Road Lexington, KY 40510

Cross Street: Rice Rd./ Old Versailles Rd

Aid Given or Received Incident Type

Their Incident: 15103 Their FDID: 34155 Their State: KY Aircraft fire Mutual aid given

Shifts & Alarms Dates & Times

Shift or Platoon: 2 08/27/2006 06:13 AM Arrival: Alarms: 1 Controlled: 08/27/2006 06:19 AM 204 08/28/2006 06:00 PM District: Cleared:

Estimated Dollar Losses & Values **Actions Taken** Resources

**EMS** 

LOSSES Property: \$25,000,000.00 Apparatus Personnel Fire control or extinguishment, other Suppression 2 2 Contents: \$0.00 Notify other agencies.

4

PRE-INCIDENT VALUE Property: \$25,000,000.00 0 Provide basic life support (BLS)

Contents: \$0.00 2 10 Other

**Hazardous Materials Release** Mixed Use Property Casualties

Diesel fuel/fuel oil - vehicle fuel tank/portable Farm use Deaths Injuries

Detector 0 Property Use Fire Service 0

Open land or field Civilian 49 1

Person/Entity Involved

Business Name: Comair Inc. Phone Number: Name:

77 COM AIR Boulevard

ERLANGER, KY 41018

Owner

Business Name: Name: Phone Number:

Authorization

ID: 400 Date: 08/27/2006 Officer: Scott Lanter

Rank: Chief Assignment:

Date: 08/27/2006 ID: 402 Member: Richard Graham

Rank: Asst Chief Assignment:

#### Remarks

Responded to an aircraft crash off the end of R/W8 on a local farm. First responding units were two crash trucks and two police patrol units. Police units were first on the scene and found the aircraft fully involved with fire. They found one victim in the cockpit area and pulled him to safety. The first in crash truck started applying foam to the aircraft, after knockdown hand lines were pulled to finish extinguishment and start searching for survivors.

Wednesday August 30, 2006 Page 2

## Blue Grass Airport DPS Incident Report - 410

Station: 34 Exposure: 0 Alarm Date: 08/2//2006 06:05:00	Station: 34	Exposure: 0	Alarm Date: 08/27/2006 06:05:00 AM	Λ
---	-------------	-------------	------------------------------------	---

The second in crash truck also helped with fire suppression and set up some lighting on the scene. Lexington Fire and Police arrived on the scene and started a wider search of the area and supplied water to the crash trucks. No other survivors were located.

Approximately 450 Gallons of foam was used off the two crash trucks and approximately 4500 gallons of water was used. Two (2), inch and three quarter hand lines were pulled one from each truck. After the initial response with a traditional tactical command system a unified command system was setup involving several local, state and federal officials.

was setup involving several local, state and federal officials	S.			
After the initial response the total number of responding air	port police and fire	personal were six	teen.	
The aircraft was a CRJ-100 operated by Comair, Flight nur	mber 5191 with 50 s	ouls onboard.		
NFIRS-2 Fire	Exposure Report:	Yes		
Property Details				
Not Residential				
Buildings Not Involved				
Acres Burned: Less Than One				
On-Site Materials or Products		Storage Use		
Aircraft, other		Bulk storage of	r warel	nousing
lgnition			Huma	n Factors Contributing To Ignition
Area of Fire Origin: Fuel tank, fuel line				Asleep
Heat Source: Heat from powered equipment, other				Possibly Impaired by Alcohol or Drugs
Item First Ignited: Flammable liquid/gas - uncontained				Unattended Person
Type of Material First Ignited: Flammable or combustible liquid, other				Possibly Mentally Disabled
Mobile Property Involved: Involved in ignition and burned				Physically Disabled
Cause of Ignition			X	Multiple Persons Involved
Cause under investigation				Age
Factors Contributing To Ignition			Est	imated Age: 0 - Female
Collision, knock down, run over, turn over				
Factors contributing to ignition, other				
Fire Suppression Factors	Suppression Factors Equipment Involved		nition	
Biological hazard onsite	None			
Fire supression factor, other				
Poor access for firefighters				

Mobile Property Involved			Reports Attached			
Air transport vehicle, other				Pre-Fire Plan Available		
Make:			П	Arson Report		
Model: CL 600 2819	Year: 2001			Police Report		
License Plate Number:	State:	Vin#: N431CA		Coroner Report		
			X	Other Report		